


Instruction Manual

MM200

ENGLISH

- BACKLIGHT
- KICK STAND
- LEAD HOLDER
- AUTO RANGING
- DATA HOLD
- 3-3/4 DIGIT 3999 COUNT LCD



KLEIN TOOLS®

www.kleintools.com

ENGLISH

MM200 Instruction Manual

GENERAL SPECIFICATIONS

The Klein Tools MM200 is an auto-ranging multimeter. It measures AC/DC voltage, AC/DC current, resistance, capacitance, temperature, and frequency. It can also test diodes and continuity.

- **Operating Altitude:** 2000 meters
- **Relative Humidity:** 75% max operating
- **Operating Temperature:** 0°C/32°F to 40°C/104°F < 75% R.H.
- **Storage Temperature:** -20°C/-4°F to 60°C/140°F < 80% R.H.
- **Accuracy Temperature:** 18°C/64°F to 28°C/82°F < 75% R.H.
- **Temperature Coefficient:** 0.1* (specified accuracy)/°C
- **Sampling Frequency:** 3 samples per second
- **Dimensions:** 5.91" x 2.76" x 1.97"
- **Weight:** 8.36 oz.
- **Calibration:** Accurate for one year
- **CAT Rating:** CAT III 600V
- **Listing:** ETL & cETL standard UL 3111-1 listed
- **Pollution Degree:** 2
- **Accuracy:** ± (% of reading + # of least significant digits)









⚠ WARNINGS

To ensure safe operation and service of the tester, follow these instructions. Failure to observe these warnings can result in severe injury or death.


- Before each use, verify meter operation by measuring a known voltage or current.
- Never use the meter on a circuit with voltages that exceed the category based rating of this meter.
- Do not use the meter during electrical storms, or in wet weather.
- Do not use the meter or test leads if they appear to be damaged.
- Ensure meter leads are fully seated, and keep fingers away from the metal probe contacts when making measurements.
- Do not open the meter to replace batteries while the probes are connected.
- Use caution when working with voltages above 60V DC, or 25V AC RMS. Such voltages pose a shock hazard.
- To avoid false readings that can lead to electrical shock, replace batteries if a low battery indicator appears.
- Unless measuring voltage or current, shut off and lock out power before measuring resistance or capacitance.
- Always adhere to local and national safety codes. Use individual protective equipment to prevent shock and arc blast injury where hazardous live conductors are exposed.

For Professionals... Since 1857®

SYMBOLS

	AC Alternating Current		Warning or Caution
	DC Direct Current		Dangerous Levels
	DC/AC Voltage or Current		Double Insulated Class II
	Ground		AC Source

FEATURE DETAILS



A. B. Use properly safety-rated leads.

A. Do not attempt to measure more than 600V or 400mA.

B. Do not attempt to measure more than 10A.

C. Select Functionality Button

- Switch between AC and DC.
- Switch between  and .

D. Data Hold

- Press to hold the current input on the display.
- Press again to return to live reading.


E. Select Frequency/Duty Cycle Button

- Switch between measurement, Hz, and %.

F. Backlight

- Press to enable/disable lights.
- Using lights drains the battery significantly.


G. H. Battery/Fuse Replacement

- When  indicator is displayed on the LCD, batteries must be replaced.
- Remove back screw and replace 9V battery.
- If more than 400mA is applied to **(A)**, replace with 400mA/250V fast-blow fuse.
- If more than 10A is applied to **(B)**, replace with respective 10A/500V fast-blow fuse.



Auto Power-Off

- Device will power off after 15 minutes non-use.
- Turn the dial or press a button to wake.

FUNCTION INSTRUCTIONS





1. AC/DC Voltage: < 600V




- Select AC or DC voltage source.

2. AC/DC Current (large): < 10A




- Start with this setting if current level is unknown.
- Attach red lead to "10A" input.
- Select AC or DC current source.
- Current above 10A will require fuse replacement.

3. AC/DC Current (small): < 400mA





- Attach red lead to “mAμA” input.
- Select μA or mA, and AC or DC current source.
- Current above 400mA will require fuse replacement.

4. Resistance: < 40MΩ



- ⚠ Do not attempt to measure resistance on a live circuit.


5. Diode/Continuity



Diode:

Display shows:


- Forward voltage drop if forward biased.
- “O.L.” if reverse biased.



Continuity:


- Display shows resistance.
- Buzzer sounds if less than 50Ω.

6. Capacitance < 200μF




- ⚠ Safely discharge capacitor before measurement.
- Reading may take up to 60 seconds for large capacitors.

7. Frequency (Hz)/Duty Cycle < 1MHz



- Follow AC Voltage test setup.

8. Temperature: -4° ≤ °F ≤ 1832°



- Use included thermocouple and adapter.
- Do not apply voltage to thermocouple.

SYMBOLS USED ON LCD

~	AC Measurement	---	DC Measurement
-	Negative DC Value	OL	Overload: Range Exceeded
+	Low Battery	H	Hold Active
AUTO	Auto Range Active	V	Voltage Measurement
%	Duty Cycle Mode	Hz	Frequency Mode
A	Current in Amps	Ω	Resistance in Ohms
▶	Diode Test		Continuity Test
n	Nano 10 ⁻⁹	°F	Temperature in Fahrenheit
m	Milli 10 ⁻³	F	Capacitance in Farads
μ	Micro 10 ⁻⁶	M	Mega 10 ⁶
k	Kilo 10 ³		

ELECTRICAL SPECIFICATIONS

DC Voltage Measurement

Range	Resolution	Accuracy
400mV ~ 600V	0.1mV ~ 1V	± (0.5% + 3 digits)

Overload Protection: 600V RMS

Input Impedance: > 10MΩ.

AC Voltage Measurement

Range	Resolution	Accuracy
4V ~ 600V	1mV ~ 1V	± (1.2% + 5 digits)

Overload Protection: 600V RMS
Input Impedance: > 10MΩ
Frequency: 50 ~ 60Hz
Response: Averaging

AC/DC Current Measurement

Range	Resolution	DC Accuracy	AC Accuracy
400µA ~ 400mA	0.1µA ~ 0.1mA	± (1.0% + 3 d)	± (1.2% + 3 d)
10A	0.01A	± (3.0% + 5 d)	± (3.0% + 5 d)

Overload Protection:
 • mA Input: F400mA / 250V fuse
 • 10A Input: F10A / 500V fuse
Max Input Current:
 • mA Input: 400mA DC / AC RMS
 • 10A Input: 10A DC / AC RMS

Resistance Measurement

Range	Resolution	Accuracy
400Ω ~ 4MΩ	0.1Ω ~ 0.001MΩ	± (0.8% + 4 digits)
40MΩ	0.01MΩ	± (1.5% + 4 digits)

Overload Protection: 600V RMS

Capacitance Measurement

Range	Resolution	Accuracy
4nF ~ 40µF	0.001nF ~ 0.01µF	± (3.0% + 6 digits)
200µF	0.1µF	± (4.0% + 6 digits)

Overload Protection: 600V RMS
4nF Range: Stated accuracy with film capacitor or better.

Frequency Measurement

Range	Resolution	Accuracy
9.999Hz ~ 999.9kHz	0.001Hz ~ 0.1kHz	± (0.5% + 2 digits)

Overload Protection: 600V RMS
Sensitivity: 0.7V RMS at 1MHz

Temperature Measurement

Range	Resolution	Accuracy
-4°F ~ 32°F	1°F	± (5.0% + 2 digits)
32°F ~ 1832°F	1°F	± (3.0% + 2 digits)

Overload Protection: 600V RMS
Sensor: K-type thermocouple, accuracy not listed

Duty Cycle Measurement

Range	Resolution	Accuracy
0.1% ~ 99.9%	0.1%	± (2% + 5 digits)

Overload Protection: 600V RMS
Frequency: 0.5Hz ~ 100kHz (pulsewidth > 2µsec)

Diode Test

Overload Protection	Test Current	Open Circuit Voltage
600V RMS	Appx. 0.6mA	Appx. < 1.5V DC

Continuity Test

Overload Protection	Open Circuit Voltage
600V RMS	Appx. 0.44V

WARRANTY

This product is warranted to be free from defects in materials and workmanship for a period of two years from the date of purchase. During this warranty period, Klein Tools has the option to repair or replace or refund the purchase price of any unit which fails to conform to this warranty under normal use and service. This warranty does not cover damage which occurs in shipment or failure which results from alteration, tampering, accident, misuse, abuse, neglect, or improper maintenance. Batteries and damage resulting from failed batteries are not covered by warranty. A purchase receipt or other proof of original purchase date will be required before warranty repairs will be rendered.

Any implied warranties, including but not limited to implied warranties of merchantability and fitness for a particular purpose, are limited to the express warranty. Klein Tools shall not be liable for loss of use of the instrument or other incidental or consequential damages, expenses, or economic loss, or for any claim or claims for such damage, expenses or economic loss.

Some states or countries laws vary, so the above limitations or exclusions may not apply to you. This warranty gives you specific legal rights, and you may also have other rights which vary from state to state. If your Klein product requires repair or for information on how to exercise your rights under the terms of this warranty, please contact Klein Tools at 1-877-775-5346.

CLEANING

Turn instrument off and disconnect test leads. Clean the instrument by using a damp cloth. Do not use abrasive cleaners or solvents.

STORAGE

Remove the batteries when instrument is not in use for a prolonged period of time. Do not expose to high temperatures or humidity. After a period of storage in extreme conditions exceeding the limits mentioned in the Specifications section, allow the instrument to return to normal operating conditions before using it.

DISPOSAL / RECYCLE



Caution: This symbol indicates that equipment and its accessories shall be subject to a separate collection and correct disposal.

CUSTOMER SERVICE

KLEIN TOOLS, INC.
 450 Bond Street
 Lincolnshire, IL 60069
1-877-775-5346
www.kleintools.com