



## Product Change Notification / SYST-05LZDH190

---

### Date:

07-Sep-2022

### Product Category:

Microprocessors

### PCN Type:

Document Change

### Notification Subject:

ERRATA - SAMA5D2 SIP Family Silicon Errata and Data Sheet Clarification

### Affected CPNs:

[SYST-05LZDH190\\_Affected\\_CPN\\_09072022.pdf](#)

[SYST-05LZDH190\\_Affected\\_CPN\\_09072022.csv](#)

### Notification Text:

SYST-05LZDH190

Microchip has released a new Errata for the SAMA5D2 SIP Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [SAMA5D2 SIP Family Silicon Errata and Data Sheet Clarification](#).

**Notification Status:** Final

**Description of Change:** Updated 1. Silicon Issue Summary Added in 6. Controller Area Network (MCAN): - 6.13. Frame transmitted despite confirmed transmit cancellation for CAN-FD messages with more than 8 data bytes Added in 13. Secure Digital MultiMedia Card Controller (SDMMC): - 13.3. SDMMC I/O calibration does not work

**Impacts to Data Sheet:** None

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 06 Sep 2022

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## Attachments:

[SAMA5D2 SIP Family Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

ATSAMA5D225C-D1M-CU  
ATSAMA5D225C-D1M-CUR  
ATSAMA5D27C-D1G-CU  
ATSAMA5D27C-D1G-CUR  
ATSAMA5D27C-D5M-CU  
ATSAMA5D27C-D5M-CUR  
ATSAMA5D27C-LD1G-CU  
ATSAMA5D27C-LD1G-CUR  
ATSAMA5D27C-LD2G-CU  
ATSAMA5D27C-LD2G-CU22  
ATSAMA5D27C-LD2G-CUR  
ATSAMA5D27C-LD2G-CUR22  
ATSAMA5D28C-D1G-CU  
ATSAMA5D28C-D1G-CU29  
ATSAMA5D28C-D1G-CUR  
ATSAMA5D28C-D1G-CUR29  
ATSAMA5D28C-LD1G-CU  
ATSAMA5D28C-LD1G-CUR  
ATSAMA5D28C-LD2G-CU  
ATSAMA5D28C-LD2G-CUR



# MICROCHIP SAMA5D2 System in Package

## SAMA5D2 System in Package (SiP) Silicon Errata and Data Sheet Clarifications

### SAMA5D2 System in Package (SIP)

The SAMA5D2 System in Package (SIP) devices that you have received conform functionally to the current Device Data Sheet (DS60001484), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in the following table. The silicon issues are summarized in [Silicon Issue Summary](#).

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current.

Data Sheet clarifications and corrections (if applicable) are located in [Data Sheet Clarifications](#), following the discussion of silicon issues.

The Device and Revision ID values for the various SAMA5D2 SIP silicon revisions are shown in the following table.

**Table 1. SAMA5D2 SIP Silicon Device Identification**

Part Number	Silicon Revision	Device Identification	
		CHIPID_CIDR[31:0]	CHIPID_EXID[31:0]
ATSAMA5D225C-D1M-CU	C	0x8A5C08C2 or 0x8A5C08C4	0x00000053
ATSAMA5D27C-D5M-CU	C	0x8A5C08C2 or 0x8A5C08C4	0x00000032
ATSAMA5D27C-D1G-CU	C	0x8A5C08C2 or 0x8A5C08C4	0x00000033
ATSAMA5D27C-LD1G-CU	C	0x8A5C08C2 or 0x8A5C08C4	0x00000061
ATSAMA5D27C-LD2G-CU	C	0x8A5C08C2 or 0x8A5C08C4	0x00000062
ATSAMA5D28C-D1G-CU	C	0x8A5C08C2 or 0x8A5C08C4	0x00000013
ATSAMA5D28C-LD1G-CU	C	0x8A5C08C2 or 0x8A5C08C4	0x00000071
ATSAMA5D28C-LD2G-CU	C	0x8A5C08C2 or 0x8A5C08C4	0x00000072

**Note:** Refer to the "Chip Identifier (CHIPID)" and "Product Identification System" sections in the current device data sheet (DS60001476) for detailed information on chip identification and version for your specific device.

## Table of Contents

SAMA5D2 System in Package (SIP).....	1
1. Silicon Issue Summary.....	4
2. Power Supply.....	6
2.1. VDDSDMMC power supply over-consumption.....	6
3. Flexible Serial Communication Controller (FLEXCOM).....	7
3.1. FLEXCOM SMBUS alert signalling is not functional.....	7
4. Ethernet MAC (GMAC).....	8
4.1. Bad association of timestamps and PTP packets.....	8
4.2. Screening registers not working.....	8
5. Inter-IC Sound Controller (I <sup>2</sup> SC).....	9
5.1. I <sup>2</sup> SC first sent data corrupted.....	9
6. Controller Area Network (MCAN).....	10
6.1. Flexible data rate feature does not support the ISO 16845-1:2016 CRC.....	10
6.2. Needless activation of interrupt MCAN_IR.MRAF.....	10
6.3. Return of receiver from Bus Integration state after Protocol Exception Event.....	10
6.4. Message RAM/RAM Arbiter not responding in time.....	11
6.5. Data loss (payload) in case storage of a received frame has not completed until end of EOF field is reached.....	11
6.6. Edge filtering causes mis-synchronization when falling edge at Rx input pin coincides with end of integration phase.....	12
6.7. Configuration of MCAN_NBTP.NTSEG2 = '0' not allowed.....	12
6.8. Retransmission in DAR mode due to lost arbitration at the first two identifier bits.....	13
6.9. Tx FIFO message sequence inversion.....	13
6.10. Unexpected High Priority Message (HPM) interrupt.....	14
6.11. Issue message transmitted with wrong arbitration and control fields.....	15
6.12. Debug message handling state machine not reset to Idle state when CCCR.INIT is set.....	16
6.13. Frame transmitted despite confirmed transmit cancellation for CAN-FD messages with more than 8 data bytes.....	16
7. Peripheral Touch Controller (PTC).....	18
7.1. Wrong pull-up value on PD[18:3] during reset.....	18
8. Power Management Controller (PMC).....	19
8.1. Change of the field PMC_MCKR.PRES is not allowed if Master/Processor Clock Prescaler frequency is too high.....	19
9. Pulse Width Modulation Controller (PWM).....	20
9.1. Fault Protection to Hi-Z for PWMx output not functional.....	20
10. Quad Serial Peripheral Interface (QSPI).....	21
10.1. QSPI hangs with long DLYCS.....	21
11. Real-Time Clock (RTC).....	22

11.1. RTC_SR.TDERR flag is stuck at 0.....	22
11.2. Read access truncated to the first 24 bits for register RTC_TIMALR (UTC_MODE) .....	22
12. ROM Code.....	23
12.1. UART blocks USB connection to SAM-BA Monitor.....	23
12.2. JTAG_TCK on IOSET 4 pin has a wrong configuration after boot.....	23
12.3. Secure Boot Mode: AES-RSA X.509 Certificate Serial Number Length Limit.....	23
13. Secure Digital MultiMedia Card Controller (SDMMC).....	24
13.1. Software 'Reset For all' command may not execute properly.....	24
13.2. Sampling clock tuning procedure.....	24
13.3. SDMMC I/O calibration does not work.....	24
14. Secure Fuse Controller (SFC).....	25
14.1. Fuse matrix programming requires a main clock (MAINCK) frequency between 10 and 15 MHz .....	25
14.2. Fuse matrix read requires a main clock (MAINCK) frequency below 28 MHz.....	25
15. Synchronous Serial Controller (SSC).....	26
15.1. Unexpected delay on TD output.....	26
16. Two-wire Interface (TWIHS).....	27
16.1. The TWI/TWIHS Clear command does not work.....	27
17. Watchdog Timer (WDT).....	28
17.1. Restart command of WDT may reset the DDR controller.....	28
18. Data Sheet Clarifications.....	29
18.1. SAMA5D2 SiP .....	29
18.2. SAMA5D2.....	29
19. Revision History.....	30
19.1. Rev. G - 08/2022.....	30
19.2. Rev. F - 03/2022.....	30
19.3. Rev. E - 09/2021.....	30
19.4. Rev. D - 03/2021.....	30
19.5. Rev. C - 02/2020.....	31
19.6. Rev. B - 01/2020.....	31
19.7. Rev. A - 04/2019.....	31
Microchip Information.....	32
The Microchip Website.....	32
Product Change Notification Service.....	32
Customer Support.....	32
Microchip Devices Code Protection Feature.....	32
Legal Notice.....	32
Trademarks.....	33
Quality Management System.....	34
Worldwide Sales and Service.....	35

# SAMA5D2 System in Package

## Silicon Issue Summary

### 1. Silicon Issue Summary

Table 1-1. Silicon Issue Summary

Module	Item/Feature	Summary
Power Supply	VDDSDMMC power supply over-consumption	Over-consumption on VDDSDMMC power supply
FLEXCOM	FLEXCOM SMBUS alert	FLEXCOM SMBUS alert signalling is not functional
GMAC	Timestamps and PTP packets	Bad association of timestamps and PTP packets
GMAC	Screening registers not working	Screening registers (GMAC_ST1RPQx and GMAC_ST2RPQx) not working
I <sup>2</sup> SC	I <sup>2</sup> SC sent data	I <sup>2</sup> SC first sent data corrupted
MCAN <sup>(1)</sup>	CRC	Flexible data rate feature does not support CRC
MCAN <sup>(1)</sup>	MCAN_IR.MRAF interrupt	Needless activation of interrupt MCAN_IR.MRAF
MCAN <sup>(2)</sup>	Bus Integration state	Return of receiver from Bus Integration state after Protocol Exception Event
MCAN <sup>(2)</sup>	Message RAM/RAM Arbiter	Message RAM/RAM Arbiter not responding in time
MCAN <sup>(2)</sup>	Frame receiving	Data loss (payload) in case storage of a received frame has not completed until end of EOF field is reached
MCAN <sup>(1)</sup>	Edge filtering	Edge filtering causes mis-synchronization when falling edge at Rx input pin coincides with end of integration phase
MCAN <sup>(2)</sup>	MCAN_NBTP.NTSEG2	Configuration of MCAN_NBTP.NTSEG2 = '0' not allowed
MCAN <sup>(2)</sup>	DAR mode	Retransmission in DAR mode due to lost arbitration at the first two identifier bits
MCAN <sup>(2)</sup>	Tx FIFO message	Tx FIFO message sequence inversion
MCAN <sup>(2)</sup>	HPM interrupt	Unexpected High Priority Message (HPM) interrupt
MCAN <sup>(2)</sup>	Transmitted message	Issue message transmitted with wrong arbitration and control fields
MCAN <sup>(2)</sup>	Debug message handling state machine not reset	Debug message handling state machine not reset to Idle state when CCCR.INIT is set
MCAN <sup>(1)</sup>	Frame transmitted despite cancellation	Frame transmitted despite confirmed transmit cancellation for CAN-FD messages with more than 8 data bytes
PMC	PMC_MCKR.PRES field	Change of the field PMC_MCKR.PRES is not allowed if Master/Processor Clock Prescaler frequency is too high
PTC	Wrong pull-up value on PD[18:3] during reset	Incorrect pull-up value
PWM	Fault Protection to Hi-Z for PWMx output	Fault Protection to Hi-Z for PWMx output is not functional
QSPI	DLYCS delay	QSPI hangs with long DLYCS
RTC	RTC_SR.TDERR flag	RTC_SR.TDERR flag is stuck at 0
RTC	Truncated read access to RTC_TIMALR (UTC_MODE)	Read access truncated to the first 24 bits for register RTC_TIMALR (UTC_MODE)

# SAMA5D2 System in Package

## Silicon Issue Summary

.....continued		
Module	Item/Feature	Summary
ROM Code	<a href="#">UART connection to SAM-BA Monitor</a>	UART blocks USB connection to SAM-BA Monitor
ROM Code	<a href="#">JTAG_TCK</a>	JTAG_TCK on IOSET 4 pin has a wrong configuration after boot
ROM Code	<a href="#">Secure Boot Mode: AES-RSA X.509 Certificate Serial Number Length Limit</a>	The length of serial numbers is limited to 16 bytes by the ROM code.
SDMMC	<a href="#">Software 'Reset For all' command</a>	Software 'Reset For all' command may not execute properly
SDMMC	<a href="#">Sampling clock tuning procedure</a>	Sampling clock tuning procedure may freeze
SDMMC	<a href="#">SDMMC I/O calibration does not work</a>	The impedance calibration mechanism for the SDMMC I/Os does not work
SFC	<a href="#">Fuse matrix programming</a>	Fuse matrix programming requires a main clock (MAINCK) frequency between 10 and 15 MHz
SFC	<a href="#">Fuse matrix read</a>	Fuse matrix read requires a main clock (MAINCK) frequency below 28 MHz
SSC	<a href="#">TD output</a>	Unexpected delay on TD output
TWIHS	<a href="#">Clear command</a>	The TWI/TWIHS Clear command does not work
WDT	<a href="#">Restart command</a>	Restart command of WDT may reset the DDR controller

**Notes:**

1. This erratum is not relevant for CAN 2.0.
2. This erratum is applicable for CAN 2.0.



## 2. Power Supply

### 2.1 VDDSDMMC power supply over-consumption

The SAMA5D2 SiP devices listed in the table below exhibit an over-consumption of roughly 5 mA on the VDDSDMMC power rail.

Affected Devices
ATSAMA5D225C-D1M
ATSAMA5D27C-D1G
ATSAMA5D28C-D1G

#### Work around

Even if the SDMMCs are not used, the following procedure greatly reduces the over-consumption on VDDSDHC:

1. Enable the peripheral clock by setting the clock for the SDHC
  - `PMC_PCER0.PID31 = 1`
2. Launch an SDMMC calibration by setting the bits EN and ALWYSON in the `SDMMC_CALCR` register
  - `SDMMC0_CALCR = SDMMC_CALCR_ALWYSON | SDMMC_CALCR_EN`
3. Wait for the end of calibration by polling the EN bit while `(SDMMC0_CALCR & SDMMC_CALCR_EN)`;
4. Disable the SDMMC peripheral clock for the SDHC
  - `PMC_PCDR0.PID31 = 1`

With this procedure, the power consumption is reduced from ~5mA to 90µA.

### **3. Flexible Serial Communication Controller (FLEXCOM)**

#### **3.1 FLEXCOM SMBUS alert signalling is not functional**

The TWI function embedded in the FLEXCOM does not support SMBUS alert signal management.

**Work around**

If this signal is mandatory in the application, the user can use one of the standalone TWIs (TWIHS0, TWIHS1) supporting the SMBUS alert signaling.

## 4. Ethernet MAC (GMAC)

### 4.1 Bad association of timestamps and PTP packets

An issue in the association mechanism between event registers and queued PTP packets may lead to timestamps incorrectly associated with these packets.

Even if it is highly unlikely to queue consecutive packets of the same type, there is no way to know which frame the content of the PTP event registers refers to.

**Work around**

None

### 4.2 Screening registers not working

GMAC Screening registers Type 1 and Type 2 (GMAC\_ST1RPQx and GMAC\_ST2RPQx) are not working.

**Work around**

None

### 5. Inter-IC Sound Controller (I<sup>2</sup>SC)

#### 5.1 I<sup>2</sup>SC first sent data corrupted

Right after I<sup>2</sup>SC reset, the first data sent by I<sup>2</sup>SC controller on the I2SDO line is corrupted. The following data are not affected.

**Work around**

None

## 6. Controller Area Network (MCAN)

### 6.1 Flexible data rate feature does not support the ISO 16845-1:2016 CRC



**Attention:** This erratum is not relevant for CAN 2.0.

CAN-FD peripheral does not support the ISO 16845-1:2016 CRC scheme which includes the stuff bit count introduced by the ISO standardization committee.

CAN 2.0 operation is not impacted.

#### Work around

None

### 6.2 Needless activation of interrupt MCAN\_IR.MRAF



**Attention:** This erratum is applicable for CAN 2.0.

During frame reception while the MCAN is in Error Passive state and the Receive Error Counter has the value MCAN\_ECR.REC = 127, it may happen that MCAN\_IR.MRAF is set although there was no Message RAM access failure. If MCAN\_IR.MRAF is enabled, an interrupt to the Host CPU is generated.

#### Work around

The Message RAM Access Failure interrupt routine needs to check whether MCAN\_ECR.RP = '1' and MCAN\_ECR.REC = 127. In this case, reset MCAN\_IR.MRAF. No further action is required.

### 6.3 Return of receiver from Bus Integration state after Protocol Exception Event



**Attention:** This erratum is not relevant for CAN 2.0.

In case a started transmission is aborted shortly before the transmission of the FDF bit, a receiver will detect a recessive FDF bit followed by a recessive res bit. In this case receiving MCANs with Protocol Exception Event Handling enabled will detect a protocol exception event and will enter Bus Integration state. These receivers are expected to leave Bus Integration state after 11 consecutive recessive bits.

Instead of starting to count 11 recessive bits directly after entering Bus Integration state, the MCAN needs to see at least one dominant bit.

#### Work around

Disable Protocol Exception Event Handling (MCAN\_CCCR.PXHD = '1').

### 6.4 Message RAM/RAM Arbiter not responding in time



**Attention:** This erratum is applicable for CAN 2.0.

When the MCAN wants to store a received frame, and the Message RAM/RAM Arbiter does not respond in time, this message cannot be stored completely and it is discarded with the reception of the next message. Interrupt flag MCAN\_IR.MRAF is set. It may happen that the next received message is stored incomplete. In this case, the respective Rx Buffer or Rx FIFO element holds inconsistent data.

#### Work around

Configure the RAM Watchdog to the maximum expected Message RAM access delay. In case the Message RAM / RAM Arbiter does not respond within this time, the Watchdog Interrupt MCAN\_IR.WDI is set. In this case discard the frame received after MCAN\_IR.MRAF has been activated.

### 6.5 Data loss (payload) in case storage of a received frame has not completed until end of EOF field is reached



**Attention:** This erratum is applicable for CAN 2.0.

This erratum is applicable only if the MCAN peripheral clock frequency is below 77 MHz.

During frame reception, the Rx Handler needs access to the Message RAM for acceptance filtering (read access) and storage of accepted messages (write access).

The time needed for acceptance filtering and storage of a received message depends on the MCAN peripheral clock frequency, the number of MCANs connected to a single Message RAM, the Message RAM arbitration scheme, and the number of configured filter elements.

In case storage of a received message has not completed until the end of the received frame is reached, the following faulty behavior can be observed:

- The last write to the Message RAM to complete storage of the received message is omitted, this data is lost. Applies for data frames with DLC > 0, worst case is DLC = 1.
- Rx FIFO: FIFO put index MCAN\_RXFnS.FnPI is updated although the last FIFO element holds corrupted data.
- Rx Buffer: New Data flag MCAN\_NDATn.NDxx is set although the Rx Buffer holds corrupted data.
- Interrupt flag MCAN\_IR.MRAF is not set.

#### Work around

Reduce the maximum number of configured filter elements for the MCANs attached to the Message RAM until the calculated clock frequency is below the MCAN peripheral clock frequency used with the device.

### 6.6 Edge filtering causes mis-synchronization when falling edge at Rx input pin coincides with end of integration phase



**Attention:** This erratum is not relevant for CAN 2.0.

When edge filtering is enabled (MCAN\_CCCR.EFBI = '1') and when the end of the integration phase coincides with a falling edge at the Rx input pin, it may happen that the MCAN synchronizes itself wrongly and does not correctly receive the first bit of the frame. In this case the CRC will detect that the first bit was received incorrectly; it will rate the received FD frame as faulty and an error frame will be sent.

The issue only occurs when there is a falling edge at the Rx input pin (CANRX) within the last time quantum (tq) before the end of the integration phase. The last time quantum of the integration phase is at the sample point of the 11th recessive bit of the integration phase. When the edge filtering is enabled, the bit timing logic of the MCAN sees the Rx input signal delayed by the edge filtering. When the integration phase ends, the edge filtering is automatically disabled. This affects the reset of the FD CRC registers at the beginning of the frame. The Classical CRC registers are not affected, so this issue does not affect the reception of Classical frames.

In CAN communication, the MCAN may enter integrating state (either by resetting MCAN\_CCCR.INIT or by protocol exception event) while a frame is active on the bus. In this case the 11 recessive bits are counted between the Acknowledge bit and the following start of frame. All nodes have synchronized at the beginning of the dominant Acknowledge bit. This means that the edge of the following Start-of-Frame bit cannot fall on the sample point, so the issue does not occur. The issue occurs only when the MCAN is, by local errors, mis-synchronized with regard to the other nodes, or not synchronized at all.

Glitch filtering as specified in ISO 11898-1:2015 is fully functional.

Edge filtering was introduced for applications where the data bit time is at least two tq (of the nominal bit time) long. In that case, edge filtering requires at least two consecutive dominant time quanta before the counter counting the 11 recessive bits for idle detection is restarted. This means edge filtering covers the theoretical case of occasional 1-tq-long dominant spikes on the CAN bus that would delay idle detection. Repeated dominant spikes on the CAN bus would disturb all CAN communication, so the filtering to speed up idle detection would not help network performance.

When this rare event occurs, the MCAN sends an error frame and the sender of the affected frame retransmits the frame. When the retransmitted frame is received, the MCAN has left the integration phase and the frame will be received correctly. Edge filtering is only applied during integration phase; it is never used during normal operation. As the integration phase is very short with respect to "active communication time", the impact on total error frame rate is negligible. The issue has no impact on data integrity.

The MCAN enters integration phase under the following conditions:

- when MCAN\_CCCR.INIT is set to '0' after start-up
- after a protocol exception event (only when MCAN\_CCCR.PXHD = '0')

#### Work around

Disable edge filtering or wait on retransmission in case this rare event happens.

### 6.7 Configuration of MCAN\_NBTP.NTSEG2 = '0' not allowed



**Attention:** This erratum is applicable for CAN 2.0.

When MCAN\_NBTP.NTSEG2 is configured to zero (Phase\_Seg2(N) = 1), and when there is a pending transmission request, a dominant third bit of Intermission may cause the MCAN to wrongly transmit the first identifier bit dominant instead of recessive, even if this bit was configured as '1' in the MCAN's Tx Buffer Element.

A phase buffer segment 2 of length '1' (Phase\_Seg2(N) = 1) is not sufficient to switch to the first identifier bit after the sample point in Intermission where the dominant bit was detected.

The CAN protocol according to ISO 11898-1 defines that a dominant third bit of Intermission causes a pending transmission to be started immediately. The received dominant bit is handled as if the MCAN has transmitted a Start-of-Frame (SoF) bit.

The ISO 11898-1 specifies the minimum configuration range for Phase\_Seg2(N) to be 2..8 tq. Therefore excluding a Phase\_Seg2(N) of '1' will not affect MCAN conformance.

### Work around

Use the range 1..127 for MCAN\_NBTP.NTSEG2 instead of 0..127.

## 6.8 Retransmission in DAR mode due to lost arbitration at the first two identifier bits



**Attention:** This erratum is applicable for CAN 2.0.

When the MCAN is configured in DAR mode (MCAN\_CCCR.DAR = '1') the Automatic Retransmission for transmitted messages that have been disturbed by an error or have lost arbitration is disabled. When the transmission attempt is not successful, the Tx Buffer's transmission request bit (MCAN\_TXBRP.TRPxx) shall be cleared and its Cancellation Finished bit (MCAN\_TXBCF.CFxx) shall be set.

When the transmitted message loses arbitration at one of the first two identifier bits, it may happen that instead of the bits of the actually transmitted Tx Buffer, the MCAN\_TXBRP.TRPxx and MCAN\_TXBCF.CFxx bits of the previously started Tx Buffer (or Tx Buffer 0 if there is no previous transmission attempt) are written (MCAN\_TXBRP.TRPxx = '0', MCAN\_TXBCF.CFxx = '1').

If in this case the MCAN\_TXBRP.TRPxx bit of the Tx Buffer that lost arbitration at the first two identifier bits has not been cleared, retransmission is attempted.

When the MCAN loses arbitration again at the immediately following retransmission, then actually and previously transmitted Tx Buffers are the same and this Tx Buffer's MCAN\_TXBRP.TRPxx bit is cleared and its MCAN\_TXBCF.CFxx bit is set.

### Work around

None

## 6.9 Tx FIFO message sequence inversion



**Attention:** This erratum is applicable for CAN 2.0.

Assume the case that there are two Tx FIFO messages in the output pipeline of the Tx Message Handler. Transmission of Tx FIFO message 1 is started:

- Position 1: Tx FIFO message 1 (transmission ongoing)
- Position 2: Tx FIFO message 2
- Position 3: --



# SAMA5D2 System in Package

## Controller Area Network (MCAN)

---

Now a non-Tx FIFO message with a higher CAN priority is requested. Due to its priority it will be inserted into the output pipeline. The TxMH performs so called "message scans" to keep the output pipeline up to date with the highest priority messages from the Message RAM. After the following two message scans, the output pipeline has the following content:

- Position 1: Tx FIFO message 1 (transmission ongoing)
- Position 2: non-Tx FIFO message with higher CAN priority
- Position 3: Tx FIFO message 2

If the transmission of Tx FIFO message 1 is not successful (lost arbitration or CAN bus error) it is pushed from the output pipeline by the non-Tx FIFO message with higher CAN priority. The following scan re-inserts Tx FIFO message 1 into the output pipeline at position 3:

- Position 1: non-Tx FIFO message with higher CAN priority (transmission ongoing)
- Position 2: Tx FIFO message 2
- Position 3: Tx FIFO message 1

Now Tx FIFO message 2 is in the output pipeline in front of Tx FIFO message 1 and they are transmitted in that order, resulting in a message sequence inversion.

### Work around

#### 1. First Work Around

Use two dedicated Tx Buffers, e.g. use Tx Buffers 4 and 5 instead of the Tx FIFO. The pseudo-code below replaces the function that fills the Tx FIFO.

Write message to Tx Buffer 4.

Transmit loop:

- Request Tx Buffer 4 - write MCAN\_TXBAR.A4
- Write message to Tx Buffer 5
- Wait until transmission of Tx Buffer 4 completed - MCAN\_IR.TC, read MCAN\_TXBTO.TO4
- Request Tx Buffer 5 - write MCAN\_TXBAR.A5
- Write message to Tx Buffer 4
- Wait until transmission of Tx Buffer 5 is completed - MCAN\_IR.TC, read MCAN\_TXBTO.TO5

#### 2. Second Work Around

Make sure that only one Tx FIFO element is pending for transmission at any time. The Tx FIFO elements may be filled at any time with messages to be transmitted, but their transmission requests are handled separately. Each time a Tx FIFO transmission has completed and the Tx FIFO gets empty (MCAN\_IR.TFE = '1'), the next Tx FIFO element is requested.

#### 3. Third Work Around

Use only a Tx FIFO. Send the message with the higher priority also from Tx FIFO.

One drawback is that the higher priority message has to wait until the preceding messages in the Tx FIFO have been sent.

## 6.10 Unexpected High Priority Message (HPM) interrupt



**Attention:** This erratum is applicable for CAN 2.0.

This issue occurs in two configurations:

Configuration A:

# SAMA5D2 System in Package

## Controller Area Network (MCAN)

- At least one Standard Message ID Filter Element is configured with Priority flag set (S0.SFEC = "100"/"101"/"110").
- No Extended Message ID Filter Element is configured.
- Non-matching extended frames are accepted (MCAN\_GFC.ANFE = "00"/"01").

The HPM Interrupt flag MCAN\_IR.HPM is set erroneously on reception of a non-high-priority extended message under the following conditions:

1. A standard HPM frame is received, and accepted by a filter with Priority flag set. Then, Interrupt flag MCAN\_IR.HPM is set as expected.
2. Next, an extended frame is received and accepted due to the MCAN\_GFC.ANFE configuration. Then, Interrupt flag MCAN\_IR.HPM is set erroneously.

### Configuration B:

- At least one Extended Message ID Filter Element is configured with Priority flag set (F0.EFEC = "100"/"101"/"110").
- No Standard Message ID Filter Element is configured.
- Non-matching standard frames are accepted (MCAN\_GFC.ANFS = "00"/"01").

The HPM Interrupt flag MCAN\_IR.HPM is set erroneously on reception of a non-high-priority standard message under the following conditions:

1. An extended HPM frame is received, and accepted by a filter with Priority flag set. Then, Interrupt flag MCAN\_IR.HPM is set as expected.
2. Next, a standard frame is received and accepted due to the MCAN\_GFC.ANFS configuration. Then, Interrupt flag MCAN\_IR.HPM is set erroneously.

### **Work around**

#### Configuration A:

Set up an Extended Message ID Filter Element with the following configuration:

- F0.EFEC = "001"/"010" - select Rx FIFO for storage of extended frames
- F0.EFID1 = any value - value not relevant as all ID bits are masked out by F1.EFID2
- F1.EFT = "10" - classic filter, F0.EFID1 = filter, F1.EFID2 = mask
- F1.EFID2 = zero - all bits of the received extended ID are masked out

Now, all extended frames are stored in Rx FIFO 0 respectively Rx FIFO 1 depending on the configuration of F0.EFEC.

#### Configuration B:

Set up a Standard Message ID Filter Element with the following configuration:

- S0.SFEC = "001"/"010" - select Rx FIFO for storage of standard frames
- S0.SFID1 = any value - value not relevant as all ID bits are masked out by S0.SFID2
- S0.SFT = "10" - classic filter, S0.SFID1 = filter, S0.SFID2 = mask
- S0.SFID2 = zero - all bits of the received standard ID are masked out

Now, all standard frames are stored in Rx FIFO 0 respectively Rx FIFO 1 depending on the configuration of S0.SFEC.

## 6.11 Issue message transmitted with wrong arbitration and control fields



**Attention:** This erratum is applicable for CAN 2.0.

When the following conditions are met, a message with wrong ID, format, and DLC is transmitted:

- M\_CAN is in state "Receiver" (PSR.ACT = "10") and there is no pending transmission.

- A new transmission is requested before the third Intermission bit is reached.
- The CAN bus is sampled dominant at the third Intermission bit which is treated as SoF (see ISO11898-1:2015 Section 10.4.2.2).

Then, it can happen that:

- the Shift register is not loaded with the ID, format and DLC of the requested message,
- the MCAN starts arbitration with wrong ID, format, and DLC on the next bit,
- if the ID wins arbitration, a CAN message with valid CRC is transmitted,
- if this message is acknowledged, the ID stored in the Tx Event FIFO is the ID of the requested Tx message, and not the ID of the message transmitted on the CAN bus, and no error is detected by the transmitting MCAN.

### Work around

Request a new transmission only if another transmission is already pending or when the MCAN is not in "Receiver" state (when `PSR.ACT`  $\neq$  "10").

To avoid activating the transmission request in the critical time window between the sample points of the second and third Intermission bits, the application software can evaluate the Rx Interrupt flags `IR.DRX`, `IR.RF0N` and `IR.RF1N`, which are set at the last EoF bit when a received and accepted message becomes valid.

The last EoF bit is followed by three Intermission bits. Therefore, the critical time window has safely terminated three bit times after the Rx interrupt. Now a transmission can be requested by writing to `TXBAR`.

After the interrupt, the application has to take care that the transmission request for the CAN Protocol Controller is activated before the critical window of the following reception is reached.

A checksum covering the arbitration and control fields can be added to the data field of the message to be transmitted, to detect frames transmitted with wrong arbitration and control fields.

## 6.12 Debug message handling state machine not reset to Idle state when `CCCR.INIT` is set



**Attention:** This erratum is applicable for CAN 2.0.

In case `MCAN_CCCR.INIT` is set by the Host by writing to register `MCAN_CCCR` or when the CAN enters BusOff state, the debug message handling state machine stays in its current state instead of being reset to Idle state. Setting `MCAN_CCCR.CCE` does not change `MCAN_RXF1S.DMS`.

### Work around

In case the debug message handling state machine has stopped while `MCAN_RXF1S.DMS="01"` or `MCAN_RXF1S.DMS="10"`, it can be reset to Idle state by a hardware reset or by reception of debug messages after `MCAN_CCCR.INIT` is reset to zero.

## 6.13 Frame transmitted despite confirmed transmit cancellation for CAN-FD messages with more than 8 data bytes



**Attention:** This erratum is not relevant for CAN 2.0.

# SAMA5D2 System in Package

## Controller Area Network (MCAN)

---

In case the transmission of Tx Buffer nn was not successful and is restarted immediately afterwards by automatic retransmission, and the software requests a Tx cancellation for this Tx Buffer by setting the cancellation request bit MCAN\_TXBCR.CRnn during transmission of the first 4 identifier bits, a successful cancellation is incorrectly signalled by setting MCAN\_TXBCF.CFnn = '1' and by clearing MCAN\_TXBRP.TRPnn. In addition, the respective Transmission Occurred bit remains zero (MCAN\_TXBTO.TOnn = '0'), incorrectly indicating that the frame was not transmitted on the bus.

Other than signalled by MCAN\_TXBCF.CFnn and MCAN\_TXBTO.TOnn, the transmission continues until the complete frame has been sent on the CAN bus. If the transmission is successful, MCAN\_TXBTO.TOnn will be set.

If in this case new data is written to Tx Buffer nn while the transmission is still ongoing, a frame with inconsistent data may appear on the bus.

This problem is limited to the case of transmit cancellation of CAN-FD messages with more than 8 data bytes while automatic retransmission is enabled (MCAN\_CCCR.DAR = '0').

Transmit cancellation of Classical CAN messages and CAN-FD messages with up to 8 data bytes is not affected.

CAN 2.0 operation is not impacted.

### **Work around**

Do not use transmit cancellation for CAN-FD messages with more than 8 data bytes.

Alternatively, wait for the duration of the expected transmission time of the cancelled Tx Buffer before writing new data to that Tx Buffer.

## 7. Peripheral Touch Controller (PTC)

### 7.1 Wrong pull-up value on PD[18:3] during reset

The PTC ADC includes pull-up resistors ( $10\text{ k}\Omega \pm 30\%$ ) connected on PD[18:3] which are normally disabled at reset.

Because of an incorrect control of the internal pull-up disable signal, these pull-up resistors are connected temporarily to the pads at reset.

The  $10\text{ k}\Omega$  pullups are disconnected when the reset phase is completed and the internal resets have been released. The pull-up value is then  $\sim 380\text{ k}\Omega$ .

#### **Work around**

None

## 8. Power Management Controller (PMC)

### 8.1 Change of the field PMC\_MCKR.PRES is not allowed if Master/Processor Clock Prescaler frequency is too high

PMC\_MCKR.PRES cannot be changed if the clock applied to the Master/Processor Clock Prescaler (see “Master Clock Controller” in section “Power Management Controller (PMC)” of the SAMA5D2 Series data sheet) is greater than 312 MHz (VDDCORE[1.1, 1.32]) and 394 MHz (VDDCORE[1.2, 1.32]).

#### Work around

1. Set PMC\_MCKR.CSS to MAIN\_CLK.
2. Set PMC\_MCKR.PRES to the required value.
3. Change PMC\_MCKR.CSS to the new clock source (PLLA\_CLK, UPLLCK).

## 9. Pulse Width Modulation Controller (PWM)

### 9.1 Fault Protection to Hi-Z for PWMx output not functional

While it is possible to force the output of PWMH and PWML to 0 or 1, the feature to set these outputs to Hi-Z by setting the corresponding field in PWM\_FPV2 is not functional.

The protection values for PWML and PWMH are by default set to '0'.

#### **Work around**

None

## 10. Quad Serial Peripheral Interface (QSPI)

### 10.1 QSPI hangs with long DLYCS

QSPI hangs if a command is written to any QSPI register during the DLYCS delay. There is no status bit to flag the end of the delay.

#### **Work around**

The field DLYCS defines a minimum period for which Chip Select is de-asserted, required by some memories. This delay is generally < 60 ns and comprises internal execution time, arbitration and latencies. Thus, DLYCS must be configured to be slightly higher than the value specified for the slave device. The software must wait for this same period of time plus an additional delay before a command can be written to the QSPI.



## 11. Real-Time Clock (RTC)

### 11.1 RTC\_SR.TDERR flag is stuck at 0

The TDERR flag reporting internal free counters errors is stuck at 0. The non-BCD or invalid date/time values are not reported in the RTC Status register (RTC\_SR).

**Work around**

None. A software procedure to check the validity of the RTC time and date values may be implemented.

### 11.2 Read access truncated to the first 24 bits for register RTC\_TIMALR (UTC\_MODE)

The register RTC\_TIMALR (UTC\_MODE) is a 32-bit read/write register but the bits 24:31 are write only.

RTC\_TIMALR (UTC\_MODE) is functioning properly but any read after write of this register will show the value 0 for the upper byte.

**Work around**

None.

## 12. ROM Code

### 12.1 UART blocks USB connection to SAM-BA Monitor

When a UART is used as the ROM Code console interface in the Boot Configuration Word, the USB Device connection may not be properly enabled, and thus the SAM-BA Monitor does not run.

#### **Work around**

Pull up the RX line of the UART.

### 12.2 JTAG\_TCK on IOSET 4 pin has a wrong configuration after boot

The JTAG\_TCK signal on IOSET 4 shares its pin (PA22) with the clock signal of the following boot memory interfaces: SDMMC1, SPI1 IOSET 2, QSPI 0 IOSET 3.

If JTAG IOSET 4 is selected by the user as JTAG debug port in the Boot Configuration Word, and if the ROM Code boots, or tries to boot, on any of the external memory interfaces stated above, the JTAG clock pin (TCK) is reset at its default mode (PIO) at the end of the ROM Code execution.

This occurs as soon as EXT\_MEM\_BOOT\_ENABLE is set.

#### **Work around**

Do not select or disable external memory boot interface SDMMC1, SPI1 IOSET 2 or QSPI0 IOSET 3. However, if using one of these boot interfaces is required, reconfigure the PA22 pin in JTAG TCK IOSET 4 mode in the bootstrap or application.

### 12.3 Secure Boot Mode: AES-RSA X.509 Certificate Serial Number Length Limit

According to the standard RFC 5280 "Internet X.509 Public Key Infrastructure Certificate" section 4.1.2.2, the maximum length for serial numbers in X.509 certificates is 20 bytes.

When parsing the certificate chain in AES-RSA Secure Boot mode, the maximum serial number length allowed by the ROM code is 16 bytes.

#### **Work Around**

To use AES-RSA Secure Boot mode, do not use X.509 certificates with a serial number length higher than 16 bytes.

## **13. Secure Digital MultiMedia Card Controller (SDMMC)**

### **13.1 Software 'Reset For all' command may not execute properly**

The software 'Reset For All' command may not execute properly, and, as a result, some registers of the host controller may not reset properly. The setting of the different registers must be checked before reinitializing the SD card.

**Work around**

None

### **13.2 Sampling clock tuning procedure**

The sampling clock tuning procedure described in the “SD Host Controller Simplified Specification V3.00” may freeze in the latest verification of the “Wait until Buffer Read Ready” condition.

**Work around**

The condition “Check Execute Tuning = 0” can be *OR'ed* to “Wait until Buffer Read Ready” condition in the loop issuing the *SEND\_TUNING\_BLOCK* command (CMD19).

### **13.3 SDMMC I/O calibration does not work**

The impedance calibration mechanism for the SDMMC I/Os does not work. A fixed calibration code is internally hard-wired and, as a result, the calibration procedure described in the device data sheet, section “ I/O Calibration”, has no effect.

The I/O impedance values are given in the section "Electrical Characteristics" of the data sheet.

With these values and careful PCB design (impedance controlled and matched traces), the SDMMC can be operated in HS200 and in SDR104 modes up to 120 MHz .

**Work around**

None

## 14. Secure Fuse Controller (SFC)

### 14.1 Fuse matrix programming requires a main clock (MAINCK) frequency between 10 and 15 MHz

If the main clock is not within the range of 10 to 15 MHz while programming the fuse matrix, the correct fuse programming cannot be ensured.

#### Work around

- If the main clock is out of the 10 to 15 MHz range, then before programming the fuse matrix switches the main clock to the internal 12 MHz RC oscillator.
- To program the fuses during ROM Code execution, SAM-BA/Secure and SAM-BA version 3.2.2 or higher must be used.

### 14.2 Fuse matrix read requires a main clock (MAINCK) frequency below 28 MHz

If the main clock is higher than 28 MHz, fuse matrix content read cannot be ensured.

#### Work around

Do not use the main oscillator in Bypass mode with a frequency higher than 28 MHz.

## 15. Synchronous Serial Controller (SSC)

### 15.1 Unexpected delay on TD output

When SSC is configured with the following conditions:

- RCMR.START = Start on falling edge/Start on Rising edge/Start on any edge,
- RFMR.FSOS = None (input),
- TCMR.START = Receive Start,

an unexpected delay of 2 or 3 system clock cycles is added to the TD output.

#### **Work around**

None

## 16. Two-wire Interface (TWIHS)

### 16.1 The TWI/TWIHS Clear command does not work

Bus reset using the “CLEAR” bit of the TWI/TWIHS control register does not work correctly during a bus busy state.

#### **Work around**

When the TWI master detects the SDA line stuck in low state the procedure to recover is:

1. Reconfigure the SDA/SCL lines as PIO.
2. Try to assert a Logic 1 on the SDA line (PIO output = 1).
3. Read the SDA line state. If the PIO state is a Logic 0, then generate a clock pulse on SCL (1-0-1 transition).
4. Read the SDA line state. If the SDA line = 0, go to Step 3; if SDA = 1, go to Step 5.
5. Generate a STOP condition.
6. Reconfigure SDA/SCL PIOs as peripheral.

## 17. Watchdog Timer (WDT)

### 17.1 Restart command of WDT may reset the DDR controller

When using the WDT window with WDD and WDV field of the WDT:

- if  $0 < WDD < WDV$
- and the WDT is restarted in the permitted window  $0 < \text{wdt counter} < WDD$

then the WDT is restarted but a reset signal is sent to the fuse controller and the DDR controller, leading to DDR memory access and/or fuse access issues.

#### **Work around**

None. Do not use the window mode of the WDT.

### 18. Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest versions of the device data sheets:

Device	Document Reference
SAMA5D2 SiP	DS60001484
SAMA5D2	DS60001476

**Note:** Corrections in tables, registers, and text are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

#### 18.1 SAMA5D2 SiP

No clarifications to report at this time.

#### 18.2 SAMA5D2

No clarifications to report at this time.



## 19. Revision History

### 19.1 Rev. G - 08/2022

Updated 1. [Silicon Issue Summary](#)

Added in 6. [Controller Area Network \(MCAN\)](#):

- 6.13. [Frame transmitted despite confirmed transmit cancellation for CAN-FD messages with more than 8 data bytes](#)

Added in 13. [Secure Digital MultiMedia Card Controller \(SDMMC\)](#):

- 13.3. [SDMMC I/O calibration does not work](#)

### 19.2 Rev. F - 03/2022

Updated 1. [Silicon Issue Summary](#).

Deleted in 6. [Controller Area Network \(MCAN\)](#):

- [Message order inversion when transmitting from dedicated Tx Buffers configured with same message ID](#)

### 19.3 Rev. E - 09/2021

Updated 1. [Silicon Issue Summary](#).

Added in 6. [Controller Area Network \(MCAN\)](#):

- 6.12. [Debug message handling state machine not reset to Idle state when CCCR.INIT is set](#)

- [Message order inversion when transmitting from dedicated Tx Buffers configured with same message ID](#)

Added in 17. [Watchdog Timer \(WDT\)](#):

- 17.1. [Restart command of WDT may reset the DDR controller](#)

### 19.4 Rev. D - 03/2021

Updated [Table 1. SAMA5D2 SIP Silicon Device Identification](#).

Updated 1. [Silicon Issue Summary](#).

Added in 4. [Ethernet MAC \(GMAC\)](#):

- [Screening registers not working](#)

Added in 7. [Peripheral Touch Controller \(PTC\)](#):

- 7.1. [Wrong pull-up value on PD\[18:3\] during reset](#)

Added in 12. [ROM Code](#):

- 12.3. [Secure Boot Mode: AES-RSA X.509 Certificate Serial Number Length Limit](#)

### 19.5 Rev. C - 02/2020

Added in 11. [Real-Time Clock \(RTC\)](#):

- 11.1. [RTC\\_SR.TDERR](#) flag is stuck at 0
- 11.2. [Read access truncated to the first 24 bits for register RTC\\_TIMALR \(UTC\\_MODE\)](#) .

Updated in 12. [ROM Code](#):

- 12.1. [UART blocks USB connection to SAM-BA Monitor](#)

### 19.6 Rev. B - 01/2020

Added 12.1. [UART blocks USB connection to SAM-BA Monitor](#).

Updated 18. [Data Sheet Clarifications](#) for SAMA5D2.

### 19.7 Rev. A - 04/2019

First issue.

## Microchip Information

---

### The Microchip Website

---

Microchip provides online support via our website at [www.microchip.com/](http://www.microchip.com/). This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

### Product Change Notification Service

---

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to [www.microchip.com/pcn](http://www.microchip.com/pcn) and follow the registration instructions.

### Customer Support

---

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: [www.microchip.com/support](http://www.microchip.com/support)

### Microchip Devices Code Protection Feature

---

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable". Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

### Legal Notice

---

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded

by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at [www.microchip.com/en-us/support/design-help/client-support-services](http://www.microchip.com/en-us/support/design-help/client-support-services).

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

## Trademarks

---

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntellIMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2022, Microchip Technology Incorporated and its subsidiaries. All Rights Reserved.

ISBN: 978-1-6683-1155-4

AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamIQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro,  $\mu$ Vision, Versatile are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere.

## Quality Management System

---

For information regarding Microchip's Quality Management Systems, please visit [www.microchip.com/quality](http://www.microchip.com/quality).

## Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
<p><b>Corporate Office</b> 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Tel: 480-792-7277 Technical Support: <a href="http://www.microchip.com/support">www.microchip.com/support</a> Web Address: <a href="http://www.microchip.com">www.microchip.com</a></p> <p><b>Atlanta</b> Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455</p> <p><b>Austin, TX</b> Tel: 512-257-3370</p> <p><b>Boston</b> Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088</p> <p><b>Chicago</b> Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075</p> <p><b>Dallas</b> Addison, TX Tel: 972-818-7423 Fax: 972-818-2924</p> <p><b>Detroit</b> Novi, MI Tel: 248-848-4000</p> <p><b>Houston, TX</b> Tel: 281-894-5983</p> <p><b>Indianapolis</b> Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380</p> <p><b>Los Angeles</b> Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800</p> <p><b>Raleigh, NC</b> Tel: 919-844-7510</p> <p><b>New York, NY</b> Tel: 631-435-6000</p> <p><b>San Jose, CA</b> Tel: 408-735-9110 Tel: 408-436-4270</p> <p><b>Canada - Toronto</b> Tel: 905-695-1980 Fax: 905-695-2078</p>	<p><b>Australia - Sydney</b> Tel: 61-2-9868-6733</p> <p><b>China - Beijing</b> Tel: 86-10-8569-7000</p> <p><b>China - Chengdu</b> Tel: 86-28-8665-5511</p> <p><b>China - Chongqing</b> Tel: 86-23-8980-9588</p> <p><b>China - Dongguan</b> Tel: 86-769-8702-9880</p> <p><b>China - Guangzhou</b> Tel: 86-20-8755-8029</p> <p><b>China - Hangzhou</b> Tel: 86-571-8792-8115</p> <p><b>China - Hong Kong SAR</b> Tel: 852-2943-5100</p> <p><b>China - Nanjing</b> Tel: 86-25-8473-2460</p> <p><b>China - Qingdao</b> Tel: 86-532-8502-7355</p> <p><b>China - Shanghai</b> Tel: 86-21-3326-8000</p> <p><b>China - Shenyang</b> Tel: 86-24-2334-2829</p> <p><b>China - Shenzhen</b> Tel: 86-755-8864-2200</p> <p><b>China - Suzhou</b> Tel: 86-186-6233-1526</p> <p><b>China - Wuhan</b> Tel: 86-27-5980-5300</p> <p><b>China - Xian</b> Tel: 86-29-8833-7252</p> <p><b>China - Xiamen</b> Tel: 86-592-2388138</p> <p><b>China - Zhuhai</b> Tel: 86-756-3210040</p>	<p><b>India - Bangalore</b> Tel: 91-80-3090-4444</p> <p><b>India - New Delhi</b> Tel: 91-11-4160-8631</p> <p><b>India - Pune</b> Tel: 91-20-4121-0141</p> <p><b>Japan - Osaka</b> Tel: 81-6-6152-7160</p> <p><b>Japan - Tokyo</b> Tel: 81-3-6880-3770</p> <p><b>Korea - Daegu</b> Tel: 82-53-744-4301</p> <p><b>Korea - Seoul</b> Tel: 82-2-554-7200</p> <p><b>Malaysia - Kuala Lumpur</b> Tel: 60-3-7651-7906</p> <p><b>Malaysia - Penang</b> Tel: 60-4-227-8870</p> <p><b>Philippines - Manila</b> Tel: 63-2-634-9065</p> <p><b>Singapore</b> Tel: 65-6334-8870</p> <p><b>Taiwan - Hsin Chu</b> Tel: 886-3-577-8366</p> <p><b>Taiwan - Kaohsiung</b> Tel: 886-7-213-7830</p> <p><b>Taiwan - Taipei</b> Tel: 886-2-2508-8600</p> <p><b>Thailand - Bangkok</b> Tel: 66-2-694-1351</p> <p><b>Vietnam - Ho Chi Minh</b> Tel: 84-28-5448-2100</p>	<p><b>Austria - Wels</b> Tel: 43-7242-2244-39 Fax: 43-7242-2244-393</p> <p><b>Denmark - Copenhagen</b> Tel: 45-4485-5910 Fax: 45-4485-2829</p> <p><b>Finland - Espoo</b> Tel: 358-9-4520-820</p> <p><b>France - Paris</b> Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79</p> <p><b>Germany - Garching</b> Tel: 49-8931-9700</p> <p><b>Germany - Haan</b> Tel: 49-2129-3766400</p> <p><b>Germany - Heilbronn</b> Tel: 49-7131-72400</p> <p><b>Germany - Karlsruhe</b> Tel: 49-721-625370</p> <p><b>Germany - Munich</b> Tel: 49-89-627-144-0 Fax: 49-89-627-144-44</p> <p><b>Germany - Rosenheim</b> Tel: 49-8031-354-560</p> <p><b>Israel - Ra'anana</b> Tel: 972-9-744-7705</p> <p><b>Italy - Milan</b> Tel: 39-0331-742611 Fax: 39-0331-466781</p> <p><b>Italy - Padova</b> Tel: 39-049-7625286</p> <p><b>Netherlands - Druen</b> Tel: 31-416-690399 Fax: 31-416-690340</p> <p><b>Norway - Trondheim</b> Tel: 47-72884388</p> <p><b>Poland - Warsaw</b> Tel: 48-22-3325737</p> <p><b>Romania - Bucharest</b> Tel: 40-21-407-87-50</p> <p><b>Spain - Madrid</b> Tel: 34-91-708-08-90 Fax: 34-91-708-08-91</p> <p><b>Sweden - Gothenberg</b> Tel: 46-31-704-60-40</p> <p><b>Sweden - Stockholm</b> Tel: 46-8-5090-4654</p> <p><b>UK - Wokingham</b> Tel: 44-118-921-5800 Fax: 44-118-921-5820</p>