

Product Information

KHP 81

Part no. T0051516899

Description

Safety rest with Stop + go function. Operated by a fibre optic sensor for use with WSP80 soldering iron and WFE extraction unit.

The unit comprises :-

WDH 10 safety rest part no. T0051516172

KHP pneumatic control unit part no. T0058735818.

KHE 81

Part no. T0051516799

Description

Safety rest with Stop + go function, operated by a fibre optic sensor for use with WSP80 soldering iron and WFEP extraction unit.

The unit comprises :-

WDH 10 safety rest part no. T0051516172

KHE electric control unit part no. T0058735819.

Operation

The safety rests with stop + go functions are recommended accessories for use with WP80FE soldering irons used with the WFE or WFEP bench top fume extraction units. A fibre optic sensor switches the extraction unit on, when the soldering iron is removed from the rest and after a short delay the extraction unit is switched off when the soldering iron is replaced in the rest.

Advantage

This will reduce energy cost and increase the time between servicing by lengthening the life of the filters in the extraction units.

Associated product.

For use with KHE81 /KHP81, a second safety rest with fibre optic sensor to extend the use of the fume extraction unit to operate with two WSP80 FE soldering irons.

Part no T0051516172.

