

# **Datasheet**

**Panasonic INDUSTRY** 

# **6in1 Sensor: EWTS5GNC21**

# **6DoF Inertial Sensor for Automotive**

## **Overview**

The 6in1 sensor is a 6DoF inertial sensor with functional safety standard ISO26262 compliance for automotive applications. The sensor consists of 3 acceleration and 3 rate sensing elements on a single MEMS chip. The MEMS, ASIC, and Cap are directly bonded at wafer level and packaged. This enables the 6in1 sensor to be compact, highly accurate, easy to install, and highly reliable.

## **Feature**

- Functional Safety compliance (ISO26262) for automotive safety systems. Compatible with ASIL-D functional safety system development
- 6DoF sensors on one single MEMS chip with high accuracy for more system design flexibility
- Orthogonality:  $\leq 0.01^\circ$  between Gyro and Acceleration axis. Enable compact and simple ECU system design
- 6in1 sensor package size: 4.5 x 4.5 x 1.1 mm
- RoHS compliance

# **Application**

### **Automotive application**

- Traction control systems (TCS)
- Electronic stability control (ESC)
- Roll stability control (RSC)
- Pitch stability control (PSC)
- Rollover airbag systems (ROS)
- Adaptive cruise control (ACC)
- Adaptive front-lighting systems (AFS)
- Other safety chassis stability

### **Non-automotive application**

- **Motorcycle**
- Agriculture or construction machine
- AGV or AMR and Forklift
- Industrial robot

# **Typical Operating Circuit**



# **Table of Contents**





# <span id="page-2-0"></span>1 NOTICE ITEMS

## 1.1 THE APPLIED LAWS AND REGULATIONS

- 1) No ODCs or other ozone-depleting substances which are subject to regulation under the Montreal Protocol are used in our manufacturing processes
- 2) This product complies with the RoHS Directive (Restriction of the use of certain Hazardous Substances in electrical and electronic equipment (DIRECTIVE 2011/65/EU and (EU)2015/863).
- 3) All the materials used in this part are registered material under the "Law Concerning the Examination and Regulation of Manufactures etc. of Chemical substances".
- 4) If you need the notice by letter of "A preliminary judgment on the Laws of Japan foreign exchange and Foreign Trade control", please let us know.

# <span id="page-3-0"></span>2 DIMENSION DRAWING AND MEASUREMENT DIRECTION

## 2.1 DIMENSION DRAWING



*Figure 2-1 Dimension Drawing "Top View" (left) "Bottom View" (right)*

## 2.2 MARKING INFORMATION





## 2.3 MEASUREMENT DIRECTION



# <span id="page-4-0"></span>3 ENVIRONMENTAL CONDITIONS



*Table 3-1 Environmental Conditions*

# <span id="page-4-1"></span>4 SENSOR CHARACTERISTICS SPECIFICATION

VDD = 3.0 V to 3.6 V, Ta = -40degC to 125degC unless otherwise noted.

## 4.1 GYRO SENSOR





 $^{*1}$  FS means guaranteed measurement range (±300, ±150, ±120, ±60, or ±30dps).

<sup>\*2</sup> After being mounted and calibrated on the system side at rest.

## 4.2 ACCELERATION SENSOR

<span id="page-5-0"></span>



## 4.3 TEMPERATURE SENSOR

*Table 4-3 Temperature Sensor Characteristics Specification*

	<b>Item</b>	<b>Condition</b>		Specification	<b>Unit</b>	<b>Note</b>	
No.			<b>Min</b>	<b>Typ</b>	Max		
1	<b>Guaranteed Measurement Range</b>		-40	$\overline{\phantom{a}}$	$+125$	$^{\circ}$ C	
$\overline{2}$	Output @25°C (Typ)		$\overline{\phantom{a}}$	0000h	$\overline{\phantom{a}}$	<b>LSB</b>	2's complement
3	Output Error (Total) @ 25°C	Over life	$-10$	$\overline{\phantom{a}}$	$+10$	$^{\circ}$ C	
4	Sensitivity (Typ)		$\overline{\phantom{a}}$	20	$\sim$	$LSB$ <sup>o</sup> C	
5	Sensitivity Error (Total)	Over life	$-5$	٠	$+5$	%	
6	Linearity error		$-2$		$+2$	%FS	FS means 165°C (-40°C to 125°C)
$\overline{7}$	<b>Output Noise</b>				0.5	°C rms	
8	Hysteresis	+25°C→+125°C→+25°C  $\rightarrow$ -40 $^{\circ}$ C $\rightarrow$ +25 $^{\circ}$ C	$-5$		$+5$	$^{\circ}$ C	

 $^{*3}$  FS means guaranteed measurement range ( $\pm 16$ ,  $\pm 8$ ,  $\pm 2$ , or  $\pm 1$ G).

<sup>\*4</sup> After being mounted and calibrated on the system side at rest.



## <span id="page-6-0"></span>4.4 FREQUENCY AFFECTING TO THE SENSOR



#### *Table 4-4 Frequency Affecting To The Sensor*



## 4.5 DEFINITION OF TERMS

### 4.5.1 Guaranteed Measurement Range

A Guaranteed measurement range is a measurement range that Panasonic guarantees by either design, characterization, production test or combination of some of them. However, the actual full-scale range that the sensor can detect and express in a 16-bit frame with 2's complement is wider than this guaranteed measurement range. This is because Panasonic needs to guarantee that the sensor output does not saturate, even including the sensitivity error and the offset error. For example, the gyro sensor's default guaranteed measurement range is  $\pm 300$ dps while the full-scale range is  $\pm 655$ dps (2<sup>15</sup>[LSB] / 50[LSB/dps]). Relationships between input and output in default settings are shown in [Figure 4-1.](#page-7-0)







Temperature sensor



<span id="page-7-0"></span>



### 4.5.2 Start Up Time

Interval time from power-supply-on or hardware-reset until the startup self-test is finished and the sensor outputs get stabilized into the specified range. Please note that in case users need to configure some settings (for example low pass filter cutoff frequency, guaranteed measurement range, and etc.) of the 6in1 sensor by sending SPI commands, the users need to do these after waiting for this start-up time. In other words, the time for this manual sensor configuration change by users is not included in this start-up time.

# <span id="page-8-0"></span>5 SPI SPECIFICATION

The 6in1 sensor uses SPI (Serial Peripheral Interface) to communicate with the host processor.

## 5.1 SPI INTERFACE PIN DESCRIPTION

The internal registers and memory of the 6in1 sensor can be accessed using an SPI interface at 8MHz. SPI operates in four-wire mode.





## 5.2 SPI INTERFACE OPERATION

SPI is a 4-wire synchronous serial interface that uses two control lines and two data lines. The 6in1 sensor always operates as a slave device during standard master-slave SPI operation.

With respect to the master, MOSI, MISO, and SCLK are shared among the slave devices. Each SPI slave device requires its own Chip Select (NCS) line from the master.

NCS goes low (active) at the start of transmission and goes back high (inactive) at the end. Only one chip select line is active at any given time, ensuring that only one slave is selected at any given time. The CS lines of the non-selected slave devices are held high, causing their MISO lines to remain in a high-impedance state so that they do not interfere with any active devices.

SPI Operational Features

- 1. Data are delivered MSB first and LSB last
- 2. Data are latched on the rising edge of SCLK
- 3. Data should be transitioned on the falling edge of SCLK
- 4. The maximum frequency of SCLK is 8 MHz

SPI read and write operations are completed in 32 clock cycles.



*Figure 5-1 SPI Master/Slave Configuration* 

## 5.3 SPI INTERFACE CHARACTERISTICS

### 5.3.1 Digital Input Terminal Characteristics (SCLK, NCS, MOSI)

*Table 5-2 SPI Digital Input Terminal Characteristics (SCLK, NCS, MOSI)*



### 5.3.2 Digital Output Terminal Characteristics (MISO)

*Table 5-3 SPI Digital Output Terminal Characteristics (MISO)*



## 5.3.3 Reset Input Terminal Characteristics (RESETN)

*Table 5-4 Reset Input Terminal Characteristics (RESETN)*

<b>Items</b>	Code	Min	Typ	<b>Max</b>	<b>Unit</b>	<b>Note</b>
Input Voltage (High)	<b>VIH</b>	$0.7 \times VDDIO$		<b>VDDIO</b>	٧	
Input Voltage (Low)	<b>VIL</b>	0		$0.3 \times VDDIO$	٧	
Leak Current	IN: DIG	$-10$		10	μA	
Reset Minimum Low Period	$t_{RST}$	10			ms	

### 5.3.4 Alarm Output Terminal Characteristics (ALARMB)

*Table 5-5 Alarm Output Terminal Characteristics (ALARMB)*





## 5.3.5 Timing Characteristics

#### *Table 5-6 SPI Timing Characteristics*



#### 5.3.6 Timing Chart



*Figure 5-2 Timing Chart*

 $*$ 5 Do not operate SCLK during tcLKSU after falling NCS. When NCS falls "Low", SCLK must be set "Low" previously. \*6 Do not operate SCLK during t<sub>NCSHD</sub> before rising NCS. When NCS rises "High", SCLK must be set "Low" previously.

### 5.3.7 SPI Message Timing

The 6in1 sensor uses out-of-frame communication. The MISO responses are output in the next frame of the MOSI commands. Also, sensor internal register data is updated at the rising edges of NCS. Please note that the sensor internal ODR (Output Data Rate) is 8000 sample/s while SCLK frequency is 8MHz at maximum.



## Sensor internal register data is updated at rising edges of NCS

*Figure 5-3 SPI Message Timing*

## 5.4 SENSOR DATA ACQUISITION COMMANDS

The framework of sensor data acquisition commands is shown i[n Table 5-7.](#page-12-0) The b15 to b13 in MOSI should be b101 as to be in "Data Monitor Mode". The b11 to b8 in MOSI should be chosen fro[m Table 5-8](#page-12-1) depending on the sensor data type. The b31 to b16 in MISO is the sensor data expressed in the 16-bit 2's complement.



<span id="page-12-0"></span>

<span id="page-12-1"></span>

	<b>SADR</b>			Sensor Data Type		<b>SADR</b>				Sensor Data Type	
			b11 b10 b09 b08			b11 b10 b09 b08					
$\mathbf{0}$	$\Omega$	$\overline{0}$	0	Gyro-X-axis		$\mathbf{1}$	$\Omega$	$\mathbf{0}$	$\Omega$	<b>Accel Y-axis</b>	
$\Omega$	0	$\Omega$	1	Reserved		1	$\Omega$	$\mathbf{0}$	1	Reserved	
$\Omega$	$\Omega$	$\mathbf{1}$	0	Gyro-Y-axis		$\overline{1}$	$\Omega$	$\mathbf{1}$	$\Omega$	Accel Z-axis	
$\Omega$	0	$\mathbf{1}$	$\mathbf{1}$	Reserved		$\mathbf{1}$	$\Omega$	$\mathbf{1}$	$\mathbf{1}$	Reserved	
$\Omega$	1	$\Omega$	0	Gyro-Z-axis		$\overline{1}$	$\mathbf{1}$	$\Omega$	0	Temp 1	
$\Omega$	1	$\mathbf{0}$	1	Reserved		$\overline{1}$	$\mathbf{1}$	0	1	Temp-2	
$\mathbf{0}$	$\mathbf{1}$	$\mathbf{1}$	0	Accel X-axis		$\mathbf{1}$	$\mathbf{1}$	$\mathbf{1}$	$\mathbf 0$	$\Delta T$ (=Temp1-Temp2)	
$\Omega$		1	1	Reserved		1	$\overline{1}$	1	$\mathbf{1}$	Fixed value (AA55h)	

*Table 5-8 SADR in Data Monitor Mode*



### 5.4.1 Common Error Flag

The b15 to b14 in MISO is called as "Common Error Flag". If the 6in1 sensor's internal safety mechanisms detect any error, it becomes b01. When there is no alarm, it shows b10.

*Table 5-9 The Meaning Of Common Error Flag (b15 to b14) Bits In Data Monitor Mode MISO*

<b>Common Error Flag</b>		Function
h15 h14		
		None of all safety mechanisms has an alarm
		Any one of all safety mechanisms has an alarm

The host processor can read the same information through ALARMB terminal shown in [Table 7-1](#page-26-1) an[d Figure 8-1.](#page-27-1) ALARMB is active low, therefore the output becomes low when the common error flag becomes b01. Also, after the power-on-reset, the ALARMB becomes low from 11.5ms to 75.5ms and goes back to high, as part of the startup self-test.

### 5.4.2 X2 Bit for Data Synchronization

<span id="page-13-0"></span>The b07 is called as X2 bit. X2 bit is there to synchronize the sensor data update timing in all six axes. The meaning of the X2 bit is shown in [Table 5-10.](#page-13-0)





For example, if the host processor is to use 6-axis data, all of them can be synchronized in the following way.



Please note that X2 is set to 1 only in STEP1. At the NCS falling edge right after X2 is set to 1, new sensor data for all data types (Gyro X, Y, Z, Accel X, Y, Z, Temp1, Temp2, ∆T, and Fixed Value) are acquired and stored into the sensor internal registers. On the other hand, X2 is set to 0 after STEP1. Because of this, new sensor data will not be acquired inside of the sensor. However, the sensor data stored in the register can be retrieved through MISO one by one[. Figure 5-4](#page-13-1) shows the image of this example.



Retrieve each data one by one through MISO, but the data in the sensor internal register is not updated

<span id="page-13-1"></span>*Figure 5-4 An Example Of Data Synchronization Using X2 Bit*

### 5.4.3 KACT: 2-bit Counter

The b05 to b04 is called KACT (Keep Alive Counter). KACT is a 2-bit counter which increments every time sensor data is read. KACT increment in the up-counting order (i.e. 00  $\rightarrow$  01  $\rightarrow$  10  $\rightarrow$  11  $\rightarrow$  00  $\rightarrow$  ...). KACT increments regardless of the X2 bit setting. Also, the increment in KACT is shared with all sensor data types. KACT is only cleared by a reset or power down. [Figure 5-5](#page-14-0) shows an example of KACT counter. MOSI1, MOSI2, MOSI3, and MOSI4 mean the 1<sup>st</sup>, 2<sup>nd</sup>,3<sup>rd</sup>, and 4<sup>th</sup> byte of MOSI each. MISO is the same as well. I[n Figure 5-5,](#page-14-0) each byte is expressed in decimal.

<span id="page-14-0"></span>

*Figure 5-5 An Example Of KACT Counter*



### 5.4.4 CRC Calculation

The last four bits of the 32-bit communication protocol is CRC (Cyclic Redundancy Check) of the rest of the twenty-eight bits. Every time the host processor communicates through SPI, data integrity is checked using this CRC. The CRC is calculated in the following way.

CRC: X<sup>4</sup>+1 (Width: 4bit, Polynomial: 0x1, Initial value: 0xA)

ex. If the transferred data is "0xD07A655\*", the CRC calculation result is 0xC. (\* is CRC section.) Therefore, send data is "0xD07A655C".



*Figure 5-6 CRC Calculation*

Also, a sample code of CRC calculation is shown in [6](#page-22-0) *[Sample Source Code For A Quick Start](#page-22-0)*.



## 5.5 ERROR MESSAGES

There are two types of error messages related to SPI communication, "SPI Error" and "Unrecognized Command Error". These error messages are issued when errors occurred at any time. The error messages will be notified through MISO in the next frame. Error messages are cleared by reset, power down, or the next successful SPI communication. Also, when these errors occurred, the commands in MOSI will be ignored.

### 5.5.1 SPI Error

The SPI error is issued when SPI communication fails. The SPI error message is "0x00000903". The bit arrangement is shown in Table 5-11. SPI error occurs under any one of the following conditions.

- The number of SCLK bit count is wrong (not equal to 32)
- The CRC in the MOSI command is wrong
- Error occurred in the command decoding

*Table 5-11 SPI Error*



Also, about the wrong SCLK bit count, the 6in1 sensor handles the following way.

- In case the clock edge count is less than 32, the MOSI keeps the last received bit level while the NCS is low
- In case the clock edge count is more than 32, the MOSI keeps a low level while the NCS is low.



*Figure 5-7 SCLK Bit Count Timing*

### 5.5.2 Unrecognized Command Error

The unrecognized command error is issued when the MOSI receives undefined SPI command even though SPI communication itself is successful. The unrecognized command error message is "0x00000A00". The bit arrangement is shown in Table 5-12.







## 5.6 HOW TO CHANGE THE GUARANTEED MEASUREMENT RANGE AND THE LPF CUTOFF FREQUENCY

If needed, the host processor can change the guaranteed measurement range and the LPF cutoff frequency by changing some register values. The gyro sensor's guaranteed measurement range is selectable from ±300, ±150, ±120, ±60, and ±30 dps (the default setting is ±300 dps). The acceleration sensor's guaranteed measurement range is selectable from ±16, ±8, ±2, and ±1 G (the default setting is ±8 G). The gyro sensor's LPF cutoff frequency is selectable from 10, 12.5, 27, 30, 46, and 60 Hz (the default setting is 60Hz). The acceleration sensor's LPF cutoff frequency is selectable from 10, 46, 60, 250, 300, and 400 Hz (the default setting is 60Hz). The host processor can change these settings with the following procedures. Please note that the register is a volatile memory, and the setting is to be reset to the default value after power-on-reset. Therefore, it is highly recommended to implement a power-on-reset detection mechanism in the system.

### 5.6.1 Flow Chart Of The Overall Procedure

Flow chart of the overall procedure is shown in [Figure 5-8.](#page-17-0) After power-on, please wait for 250ms to complete the start-up. After this, please execute the LPF cutoff frequency change procedure or guaranteed measurement range change procedure if necessary.



<span id="page-17-0"></span>*Figure 5-8 Flow Chart Of Overall Guaranteed Measurement Range And LPF Cutoff Frequency Change Procedure*



### 5.6.2 LPF Cutoff Frequency Change Procedure

The flow chart of the LPF cutoff frequency change procedure is shown in [Figure 5-9.](#page-18-0) The SPI command sequence STEP 1 to STEP 15 is shown in [Table 5-13.](#page-19-0) In STEP 1 to STEP10, some bytes are varied depends on which LPF cutoff frequency setting the user chooses. Please refer t[o Table 5-14](#page-19-1) to select the appropriate byte values.



<span id="page-18-0"></span>*Figure 5-9 Flow Chart Of LPF Cutoff Frequency Change Procedure*

<span id="page-19-0"></span>



#### *Table 5-13 SPI Command Sequence To Change The LPF Cutoff Frequency*

<span id="page-19-1"></span>*Table 5-14 Individual Byte Values In The SPI Command Sequence To Change The LPF Cutoff Frequency*

Gyro	Accel	$\mathbf I$	$\mathbb{I}$	$\mathbb{I}$	$\mathbf{N}$	V	M
10Hz	10Hz	0x00	0x41	0x4B	0x4A	0x01	0x4F
10Hz	46Hz	0x00	0x82	0x44	0x45	0x02	0x4C
10Hz	60Hz	0x00	0xC3	0x41	0x40	0x03	0x4D
10Hz	250Hz	0x01	0x04	0x4B	0x4A	0x04	0x4A
10Hz	300Hz	0x01	0x45	0x4E	0x4F	0x05	0x4B
10Hz	400Hz	0x01	0x86	0x41	0x40	0x06	0x48
12.5Hz	10Hz	0x01	0xC7	0x44	0x45	0x07	0x49
12.5Hz	46Hz	0x02	0x08	0x44	0x45	0x08	0x46
12.5Hz	60Hz	0x02	0x49	0x41	0x40	0x09	0x47
12.5Hz	250Hz	0x02	0x8A	0x4E	0x4F	0x0A	0x44
12.5Hz	300Hz	0x02	0xCB	0x4B	0x4A	0x0B	0x45
12.5Hz	400Hz	0x03	0x0C	0x41	0x40	0x0C	0x42
27Hz	10Hz	0x03	0x4D	0x44	0x45	0x0D	0x43
27Hz	46Hz	0x03	0x8E	0x4B	0x4A	0x0E	0x40
27Hz	60Hz	0x03	0xCF	0x4E	0x4F	0x0F	0x41
27Hz	250Hz	0x04	0xD3	0x44	0x45	0x13	0x4C
27Hz	300Hz	0x05	0x14	0x4E	0x4F	0x14	0x4B
27Hz	400Hz	0x05	0x55	0x4B	0x4A	0x15	0x4A
30Hz	10Hz	0x05	0x96	0x44	0x45	0x16	0x49
30Hz	46Hz	0x05	0xD7	0x41	0x40	0x17	0x48
30Hz	60Hz	0x06	0x18	0x41	0x40	0x18	0x47
30Hz	250Hz	0x06	0x59	0x44	0x45	0x19	0x46
30Hz	300Hz	0x06	0x9A	0x4B	0x4A	0x1A	0x45
30Hz	400Hz	0x06	0xDB	0x4E	0x4F	0x1B	0x44
46Hz	10Hz	0x07	0x1C	0x44	0x45	0x1C	0x43
46Hz	46Hz	0x07	0x5D	0x41	0x40	0x1D	0x42
46Hz	60Hz	0x07	0x9E	0x4E	0x4F	0x1E	0x41
46Hz	250Hz	0x07	0xDF	0x4B	0x4A	0x1F	0x40
46Hz	300Hz	0x08	0xE3	0x4B	0x4A	0x23	0x4F
46Hz	400Hz	0x09	0x24	0x41	0x40	0x24	0x48
60Hz	10Hz	0x04	0x92	0x41	0x40	0x12	0x4D
60Hz	46Hz	0x09	0xA6	0x4B	0x4A	0x26	0x4B
60Hz	60Hz	0x08	0x20	0x44	0x45	0x20	0x4C
60Hz	250Hz	0x0A	0x28	0x4E	0x4F	0x28	0x45
60Hz	300Hz	0x0A	0x69	0x4B	0x4A	0x29	0x45
60Hz	400Hz	0x0A	0xAA	0x44	0x45	0x2A	0x46



#### 5.6.3 Guaranteed Measurement Range Change Procedure

The flow chart of the guaranteed measurement range change procedure is shown i[n Figure 5-10.](#page-20-0) The SPI command sequence STEP 1 to STEP 19 is shown in [Table 5-15.](#page-21-0) In STEP 10 to STEP 19, some bytes are varied depends on which guaranteed measurement range setting the user chooses. Please refer to [Table 5-16](#page-21-1) to select the appropriate byte values.



<span id="page-20-0"></span>*Figure 5-10 Flow Chart Of Guaranteed Measurement Range Change Procedure*

<span id="page-21-0"></span>



*Table 5-15 SPI Command Sequence To Change The Guaranteed Measurement Range*

*Table 5-16 Individual Byte Values In The SPI Command Sequence To Change The Guaranteed Measurement Range*

<span id="page-21-1"></span>

	<b>Guaranteed Measurement Range</b>	Sensitivity		П	Ш	<b>IV</b>	$\mathbf v$	VI
	$±300$ deg/s	50 LSB/deg/s	0x01	0x4F	0x4E			
	$±150$ deg/s	100 LSB/deg/s	0x00	0x4E	0x4F	$\overline{\phantom{a}}$		$\qquad \qquad -$
Gyro	$±120$ deg/s	133 LSB/deg/s	0x0A	0x44	0x45			
	$±60$ deg/s	267 LSB/deg/s	0x09	0x47	0x46			$\overline{\phantom{0}}$
	$±30$ deg/s	533 LSB/deg/s	0x08	0x46	0x47	$\overline{\phantom{a}}$		$\overline{\phantom{a}}$
	±16G	1000 LSB/G			$\overline{\phantom{a}}$	0x03	0x4D	0x4C
Accel.	±8G	2000 LSB/G	$\overline{\phantom{a}}$		$\overline{\phantom{a}}$	0x01	0x4F	0x4E
	±2 G	8000 LSB/G	$\overline{\phantom{a}}$		$\overline{\phantom{0}}$	0x07	0x49	0x48
	±1 G	16000 LSB/G	$\overline{\phantom{a}}$		$\overline{\phantom{0}}$	0x05	0x4B	0x4A



# <span id="page-22-0"></span>6 SAMPLE SOURCE CODE FOR A QUICK START

Below is a sample source code for a quick start that users can modify and use.







6in1 Sensor Datasheet Part Number: EWTS5GNC21



}



uint8\_t CRC\_calculation(uint8\_t data1, uint8\_t data2, uint8\_t data3, uint8\_t data4)

/\* The arguments data1, data2, data3 and data4 can be 0xD0, 0x7A, 0x65, and 0x5\* each for example. "\*" in data4 can be any numbers \*/ {

```
int initial = 0xA;
int mask = 0x0F; 
uint8_t crc;
int i ;
int temp;
data4 = data4 & 0xF0;temp = initial \lt\lt 8 | data1;
 for (i = 0; i < 8; i++) {
       if (((temp >> (11 - i)) & 1) == 1) {
            temp = temp \land (0x1 << (7 - i));
       }
  }
 temp = (temp & mask) \ll 8 | data2;for (i = 0; i < 8; i++) {
      if (((temp >> (11 - i)) & 1) == 1) {
            temp = temp \land (0x1 \ll (7 - i)); }
  }
 temp = (temp & mask) \ll 8 | data3;for (i = 0; i < 8; i++) {
      if (((temp >> (11 - i)) & 1) == 1) {
            temp = temp \land (0x1 << (7 - i)); }
  }
 temp = (temp & mask) \ll 8 | data4;for (i = 0; i < 8; i++) {
      if (((temp >> (11 - i)) & 1) == 1) {
             temp = temp ^ (0x1 << (7 - i));
       }
  }
  crc = temp & mask; //CRC
  return crc;
```
}



# <span id="page-26-1"></span><span id="page-26-0"></span>PIN DESCRIPTION

#### *Table 7-1 Pin Description*





# <span id="page-27-0"></span>8 INTERFACE CIRCUIT



*Figure 8-1 Interface Circuit (Top view)*

#### *Table 8-1 External Component List*

<span id="page-27-1"></span>

# <span id="page-28-0"></span>9 RECOMMENDED PATTERN LAYOUT

Please also refer to the [10](#page-29-0) [Notes For PCB Mounting](#page-29-0).

Terminal (Unit: mm)



*Figure 9-1 Recommended Pattern Layout*

# <span id="page-29-0"></span>10 NOTES FOR PCB MOUNTING

- Do not apply a temperature more than 265 °C to the sensor to avoid damage. Recommended reflow conditions are as follows. Please limit the reflow process only 2 times.
- To avoid multiple reflow steps for the MEMS component, the side where the MEMS is placed shall be soldered last is recommended.
- If the peak temperature is higher or if the heating time is longer than recommended, it may cause degradation of the electrical characteristics and performance over the life of the sensor. Recommended soldering condition is for the guideline for ensuring the basic characteristics of the components, does not guarantee solder joint reliability. Conditions for proper soldering should be determined by individual projects.



		<b>CONSTRAINTS</b>						
<b>Step</b>	Setting	Temp $(^{\circ}C)$	Time (sec)	Max. Rate $(^{\circ}C/sec)$				
A	$T_{\text{room}}$	25						
B	$T_{Smin}$	150						
$\mathcal{C}$	$T_{\text{Smax}}$	200	$60 < t_{BC} < 120$					
D	Liquidus	217		$r_{(T_{\text{Liquidus-TPmax})}} < 3$				
E	Pmin [255°C, 260°C]	255		$r_{(T \rightarrow Q)} < 3$				
F	T <sub>Pmax</sub> [260°C, 265°C1	260	$t_{AF}$ < 480	$r_{(T \text{Liquidus-TPmax})} < 3$				
G	Pmin [255°C, 260°C]	255	$10 < t_{FG} < 30$	$r_{(TPmax-TLiquidus)} < 4$				
H	T <sub>Liquidus</sub>	217	$60 < t_{DH} < 120$					
	$\frac{1}{\text{room}}$	25						

*Figure 10-1 Solder Reflow Profile*

- For the land of solder mask design, select the normal solder resist (both for terminal and center pad).
- Do not solder the sensor center pad to the PCB. Solder all pins (including all NC pins, but except for the center pad) to the PCB to provide mechanical stability and stress.
- Design the PCB so that the sensor center pad does not contact the PCB surface (create a gap as shown below) in the entire operating temperature range. Sensor temperature characteristics may vary due to contact between the sensor bottom and the PCB.



*Figure 10-2 Solder Joint*

- Solder all NC pins in order to secure sensor on PCB and improve solder reliability.
- For the best performance, design a ground plane in the next layer after the top layer (the top layer shall be free of traces) under the sensor to reduce signal noise from the board on which the sensor is mounted.
- Do not use ultrasonic for cleaning sensor on PCB. MEMS element may be destroyed by its ultrasonic resonance.
- Refrain from washing after mounting the sensor. Please consult in advance if necessary.
- To get the best performance from the sensor do not *use* underfill, side fill material (adhesive, etc.), and do not apply potting or molding without trials and reliability checks.
- Do not apply more than 10,000G shock to the sensor.
- Do not mount the sensor near the substrate edge or the screw mounting location. The strain applied to the sensor should be less than 500 µE (micro strains).
- The best placement of the sensor on the PCB is depending on the optimization target tilt accuracy or high frequency vibration suppression – please make sure to consider different places on the PCB. Place the sensor at least 15mm from the PCB edge if you need to suppress vibrations as it is very firmly connected to a big mass (housing, vehicle chassis). If you need to optimize inclination performance it is better to place the sensor in an area with the smallest bending stress - in the middle of the fixation points, far away from the screws, guides, or fixations.
- Do not mount the sensor near parts generating heat to avoid affecting sensor characteristics.
- Do not exceed the guaranteed operating temperature range.
- The sensor should not be mounted near the power control circuit nor high voltage source.
- Do not mount parts such as a switch and a connector on the direct opposite side of the PCB where the sensor is mounted.
- Do not place any signal trace underneath the sensor.
- Do not touch the sensor with bare hands.
- Do not re-mount the sensor. If the sensor is removed from PCB, do not re-use.
- Select PCB board and soldering material carefully not to affect sensor characteristics due to mechanical stress during sensor mounting.
- If the user uses a halogen type (Chlorine type, Bromine type, etc.) high-activity flux, need to evaluate and verify sensor and other components condition, performance, and reliability prior to applying such flux. It may affect the performance and the reliability of this product by the residue of the flux.
- Sensor mounted on PCB should not interfere or have physical contact with any surrounding components and/or any object, even under vibration.
- PCB BOM components with high mass, high center of gravity like transformers, capacitors, connectors, pushbutton switches, attached piggy packs, memory banks, etc. may be sources of vibrations and even rate signals. Understanding the origin of disturbances can be time consuming - for vibration analysis laser interferometers or cameras with stroboscopic LED lights may help to understand the source of vibrations.
- PCB Layout solder all pins of the sensor to the lands on the PCB except for the central pad. Keep the lands identical in shape and area - it is important that there is the same amount of solder at each solder joint between sensor and PCB. This allows symmetric distribution of stress caused by different thermal expansion coefficients (CTE) and perfectly flat mounting on the PCB. When focusing on measuring tilt precisely with the sensor, keep in mind on a package with a length of 4.5mm an inclination angle of 0.5 °(mech.) is equivalent to 39μm difference in height on both ends. The diameter of hairs is between 20 to 80μm. The initial error is not so critical as the measurement is mostly calibrated in software, but the strain and bending over temperature or after the mechanical shock of the complete material stack in the product are not well predictable.

# <span id="page-31-0"></span>11 HANDLING PRECAUTIONS

- Sensor package storage condition should be at  $\leq 40^{\circ}$ C,  $\leq 90\%$ R.H. And must be used within 12 months from the packing date. After opening the package, mount the sensor within 168hrs at  $\leq 30^{\circ}$ C, 60%R.H. (MSL 3).
- If overdue on the storage term, do not use the sensor. The device may experience with damage while reflow process due to the rapid evaporation from the absorbed of humidity in the package. It may lead electrical performance degradation to the device and effect to solder reliability.
- Drying conditions is  $40^{\circ}$ C,  $\leq$  5%R.H. 312hrs. Drying is required if the humidity indicator card in sealed the package shows 30% or more as opened, or storage conditions (listed above) is exceeded.
- This sensor is not designed for the extreme environment, so do not storage or use it under the following specific environment. Extreme environmental conditions, such as those listed below, might degrade the sensor performance. Verify total system performance prior to product release.
	- 1) Under any liquid, such as water, oil, chemical solution, and organic solvent.
	- 2) In direct sunlight, outdoor exposure, or dust.
	- 3) In sea breeze or corrosive gas like CI2, H2S, NH3, SO2, NOx.
	- 4) In static electricity, electromagnetic wave, or radiation
	- 5) Where the product is close to a heat-generating component, or where an inflammable such as polyvinyl chloride (PVC) insulated wire.
	- 6) In sealed or coated with resin, etc. product.
	- 7) Flux cleaning by solvent, water, or aqueous solution. (Particularly water-soluble flux.)
	- 8) Condensation.
	- 9) Use the product in a contaminated condition and environment. (Do not handle the sensor mounted on PCB directly with hands with skin moisturizer cream.)
	- Do not disassemble and modify this sensor.
	- Do not throw the sensor into the fire, apply high temperature or close to a high heat source.
	- If this product is dropped on to flor or another hard surface, it could be damaged mechanically or electrically. Do not use the dropped sensor.
	- PCB substrate resonance by external vibration (frequency band described in [4.4\)](#page-6-0) might damage MEMS. After installing the sensor to the system unit, evaluate and ensure with vibration test.
	- There is a possibility that the accelerometer MEMS element could contact stoppers by applying shocks described below. About the gyro MEMS element, there is no possibility to contact the stopper below 20kHz and 3,000G.
	- Contacting stopper doesn't mean that it will cause sensor characteristic degradation immediately. Therefore, this table is just a reference value for establishing assembling shock criteria at customer production line etc. If some assembling process excess the minimum contact shock level, please evaluate adequate sample quantities with pre/post assembly process to set safe criteria for these shock limit which shall not causing sensor characteristic degradation.



*Table 11-1 Minimum shock level which lead MEMS contact to its stopper from XYZ direction*

- To dispose of the sensor, please obey local law and method.
- In handling this sensor, please take ESD measures for suppressing electrical static within the level defined by ESD HBM and ESD CDM shown in "Table 12-1 [Reliability Test Items"](#page-32-1) to your process and also for machine.

# <span id="page-32-0"></span>12 RELIABILITY TEST ITEMS

<span id="page-32-1"></span>Panasonic conducted reliability tests based on AEC-Q100 Grade 1. The main test items are described i[n Table](#page-32-1)  [12-1.](#page-32-1) Please contact Panasonic for other test items other than those listed in [Table 12-1.](#page-32-1)





# <span id="page-33-0"></span>13 PACKAGING SPECIFICATION

The 6in1 sensor will be shipped in cushioned tape and reel packing with additional inside and outside packing. Detailed information is described below. Tape & reel size comply with EIA-481, except for the sensor recognition mark orientation in the package. The details for sensor recognition mark orientation in the package are described in [Figure 13-2.](#page-33-1)

- 1) Packaging size: 500 pieces/reel
- 2) Packaging weight: approx. 1 kg
- 3) Part weight: approx. 0.08g
- 4) Reel size:



*Figure 13-1 Reel Size*

5) Carrier tape size



<span id="page-33-1"></span>*Figure 13-2 Tape Size and Detail*



6) Cover tape exfoliation intensity:0.1N – 1.3 N



*Figure 13-3 Carrier Tape detail*

7) Inside packing form

 $L \times W \times H = 345 \times 360 \times 50$  (mm)





The moisture barrier bag is compliant with ANSI/ESD S20.20 and ANSI/ESD S541 packing standard.



8) Outside Packaging form (overseas only)  $L \times W \times H = 370 \times 370 \times 250$ 1 to 4 real/box





# <span id="page-36-0"></span>14 IMPORTANT NOTICE

- Inertial measurement sensors are measuring motion like rotation, inclination, shocks, vibrations. When embedding the sensor into the application, the physical fixation of the sensor already creates inclination, rotation, vibration, stress, or bending, which are only under the control of the users. Often there are limitations that do not allow us to choose the ideal solution. Therefore, it is important to understand the potential implications of the intended realization of the application. In order to keep the sensor's intrinsic performance, the user needs to follow the description in this datasheet. Make sure to evaluate and verify sensor performance after you have installed the sensor in your application.
- Care must be taken for the supply voltage circuit design to avoid generating high voltage which is larger than the rated voltage in transient and instantaneous high voltage etc.
- Deviating from this specification may cause the sensor to malfunction and could not guarantee the sensor performance.
- We will continue to improve the quality and the reliability of the sensor, but the performance and durability result may differ depending on the use of conditions and environment.
- Be sure to confirm the sensor performance with the actual product under the actual use conditions.
- Installing the sensor to following systems or products may cause the loss of human life or other significant damage. Therefore, evaluate and incorporate failsafe design to ensure its safety (including but not limited to automotive, train, vessel, transportation system, medical equipment, aerospace, electric heating appliances, combustion/gas equipment, machining/rotating equipment, and disaster/crime prevention equipment).
	- $\circ$  The system should be equipped with a protection circuit and protection device.
	- $\circ$  The system should be equipped with redundant or other fail-safe circuits to prevent an unsafe status in the event of a single fault.
- If there is any concern related to the sensor and securing the safety of the application, please notify us promptly. Your own engineering level evaluation of the use of the sensor must be conducted.
- The technical information in this specification provides examples of our Sensors' characterizations etc. We do not guarantee the non-infringement of third party's intellectual property rights and we do not grant any license, right, or interest in our intellectual property. We do not take any responsibility if third party related right issues occur due to this sensor usage by any possibility.
- This Product Specification is the only binding description of the specifications of this product, and shall always supersede and take precedence over any other written or oral information (including by email) communicated at any time between your company and our company, whether before or after the date of this Product Specification. Any additions, deletions, or modifications to the specifications of this product shall be invalid, null and void unless a revised Product Specification is executed by both parties.



# <span id="page-37-0"></span>15 REVISION HISTORY

