
Instruction Sheet





Step 1: Strip at least 25mm of jacket off of the cable.

Pull back the braid, and retain 6mm of foil from the cable end.



Step 2: Put wires through wire management and arrange in accordance with wiring color code (T568A/B).



Step 3: Trim excess wires. The tips of the wires should protrude no more than 0.4mm.



Step 4:

Put the wire management on the IDC tower.

NOTE: The arrows on coupler to the IDC's. Then wrap the and cap should face the same drain wire (or bundled braid) direction.




Step 5:

Close the covers all the way, which will terminate the wires around the strain relief.



Step 6:


Tighten a cable tie around the strain relief to complete the assembly for one side.



Step 7: Repeat steps 1~6 to the other side to complete the

termination.

The T-Coupler can be attached to a surface using screws. For a more compact installation you can overlap the rings and use one screw between couplers.



Page 1 of 1 MN820007-A0