TE Connectivity

Product Change Notification: P-22-022150

PCN Date: 10-FEB-22

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

The PNs listed below will remain as ACTIVE status and will not be discontinued

Description of Changes

This PCN is to revise an error previously released on PCN numbers: P-21-021901 P-21-021902 P-21-021903 P-21-021904 P-21-021905 P-21-021906 P-21-021907 P-21-021908 P-21-021909 P-21-021910 P-21-021911 The PNs listed below will remain as ACTIVE status and will not be discontinued. These PNs were previously listed on a PCN for discontinuance in error. We sincerely apologize for any confusion this may have caused. Thank you.

Reason for Changes:	
Document clarification.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	**First Date To Ship** (Changed Parts Only):
Last Ship Date (Obsolete Parts Only):	**Last Date for Mixed Shipments:** (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-50871-3	NO						
1-5645502-1	NO		TYC1-5645502-1				
1-5645991-2	NO		TYC1-5645991-2				
1050720-1	NO		TYC1050720-1				
1055070-1	NO		TYC1055070-1	"2088-1230-02"			
1057377-1	NO		TYC1057377-1	"3082-2240-00"			
1059731-1	NO		TYC1059731-1				
1236009-1	NO		TYC1236009-1				
1274563-3	NO						
131241-1	NO						
2-330311-1	NO						
2-5331272-3	NO		TYC2-5331272-3				
228226-1	NO		TYC228226-1	"4-16211-8899"			
3-5331677-8	NO		TYC3-5331677-8				
5225398-7	NO		TYC5225398-7				
5228686-1	NO		TYC5228686-1				
5415025-2	NO		TYC5415025-2				
645512-1	NO		TYC645512-1				
645519-1	NO						
787004-3	NO		TYC787004-3				

TE Connectivity

Product Change Notification: P-22-022150

PCN Date: 10-FEB-22

Customer: TTI, Inc. (3057778) **Location:** Maisach-gernlinden **Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

The PNs listed below will remain as ACTIVE status and will not be discontinued

Description of Changes

This PCN is to revise an error previously released on PCN numbers: P-21-021901 P-21-021902 P-21-021903 P-21-021904 P-21-021905 P-21-021906 P-21-021907 P-21-021908 P-21-021909 P-21-021910 P-21-021911 The PNs listed below will remain as ACTIVE status and will not be discontinued. These PNs were previously listed on a PCN for discontinuance in error. We sincerely apologize for any confusion this may have caused. Thank you.

Reason for Changes:

Document clarification.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	**First Date To Ship** (Changed Parts Only):
Last Ship Date (Obsolete Parts Only):	**Last Date for Mixed Shipments:** (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-5645502-1	NO		TYC1-5645502-1				
1055070-1	NO		TYC1055070-1	"2088-1230-02"			
3-5331677-8	NO		TYC3-5331677-8				
787004-3	NO		TYC787004-3				