

Product Ident
CT-Fuseholder-2

Control-Transformer Accessory Datasheet




Identification

Type Designation	CT-Fuseholder-2	Series	CT
Description	Fuseholder Kit		

Technical Data

Max Rated Voltage	[V]	600
Max Rated Current	[A]	30
Wire Gauge	[AWG]	12

Connection Diagram



Installation Information

Install fuseholder on top by using 2x M4 and 2x 4mm serrated washers (included). Please take care not to cover the terminal identification.
Connect F1 & F2 with primary and F3 with secondary side of the transformer.
This kit is to be used with 2000 and 2500VA CT-Transformers. Fuses are not included.

Variations may apply due to material's and production's tolerances. Objected to modifications without notice.

Original Date:	09/21/2017
Name:	Wesner
Date:	
Checked:	

Observe protection clause to ISO 16016

Index	0
Doc. type	Datasheet
Pages	1 of 1