



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000872

DATE: 07-Aug-2018

## PRODUCT DISCONTINUANCE NOTICE

| Notice Type          | Maxim Part Number  | Recommended Replacement | Last Order Date | Last Delivery Date | Reason   |
|----------------------|--------------------|-------------------------|-----------------|--------------------|--|
| Reactivation         | MAX15000AEUB+      | N/A                     |                 |                    | Part reactivated from prior notice: M000870              |
| Reactivation         | MAX15000AEUB+T     | N/A                     |                 |                    | Part reactivated from prior notice: M000870              |
| Reactivation         | MAX20094ATIA/VY+   | N/A                     |                 |                    | Part reactivated from prior notice: M000866              |
| Reactivation         | MAX20098ATEA/VY+   | N/A                     |                 |                    | Part reactivated from prior notice: M000867              |
| Lead-Free Conversion | DS2433X-300-EC#TW  | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part is leaded. Request information on lead-free version |
| Discontinuance       | 73M1903-IM/F       | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 73M1903-IMR/F      | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 73M1906B-IMR/F     | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 73M1906B-IVT/F     | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 73M1906B-IVTR/F    | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 73M1916-IVT/F      | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 73M1916-IVTR/F     | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 73S1215F-68IM/F    | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 73S8009R-IM/F      | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 73S8009R-IMR/F     | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 78P2342JAT-IGT/F   | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 78P2344JAT-IGT/F   | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 78P2344JAT-IGTR/F  | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | 78Q2120C09-64CGT/F | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | DS1809Z-050+       | N/A                     | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | MAX14576EVB+       | MAX14576CVB+            | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | MAX14576EVB+T      | MAX14576CVB+T           | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | MAX14636EVB+       | MAX14636CVB+            | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | MAX14637EVB+       | MAX14637CVB+            | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | MAX14637EVB+T      | MAX14637CVB+T           | 07-Aug-2019     | 06-Feb-2020        | Part can no longer be manufactured                       |
| Discontinuance       | MAX16933ATIR/VY+   | MAX16933CATIR/VY+       | 07-Aug-2018     | 07-Aug-2018        | The part was not released                                |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 07-Sep-2018

|                |                 |                |             |             |                                    |
|----------------|-----------------|----------------|-------------|-------------|------------------------------------|
| Discontinuance | MAX21000+TWCHS  | N/A            | 07-Aug-2019 | 06-Feb-2020 | Part can no longer be manufactured |
| Discontinuance | MAX2141ETH+     | N/A            | 07-Aug-2018 | 07-Aug-2018 | Part can no longer be manufactured |
| Discontinuance | MAX30033CTA+    | MAX30034CTA+   | 07-Aug-2019 | 06-Feb-2020 | The part was not released          |
| Discontinuance | MAX66240ETB-A+  | MAX66240ETB+   | 07-Aug-2018 | 07-Aug-2018 | Part can no longer be manufactured |
| Discontinuance | MAX66240ETB-A+T | MAX66240ETB+T  | 07-Aug-2018 | 07-Aug-2018 | Part can no longer be manufactured |
| Discontinuance | MAX66240ISA+    | MAX66240ESA+   | 07-Aug-2018 | 07-Aug-2018 | Part can no longer be manufactured |
| Discontinuance | MAX66242ETB-A+  | MAX66242ETB+   | 07-Aug-2019 | 06-Feb-2020 | Part can no longer be manufactured |
| Discontinuance | MAX66242ETB-A+T | MAX66242ETB+T  | 07-Aug-2019 | 06-Feb-2020 | Part can no longer be manufactured |
| Discontinuance | MAX66242ISA-A+  | MAX66242ESA+   | 07-Aug-2019 | 06-Feb-2020 | Part can no longer be manufactured |
| Discontinuance | MAX66242ISA-A+T | MAX66242ESA+T  | 07-Aug-2019 | 06-Feb-2020 | Part can no longer be manufactured |
| Discontinuance | MAX9217ECM+CPG  | MAX9217ECM+    | 07-Aug-2019 | 06-Feb-2020 | The part was not released          |
| Discontinuance | MAX9288GTM+     | MAX9288GGM/VY+ | 07-Aug-2018 | 07-Aug-2018 | The part was not released          |
| Discontinuance | MAX9860ETG+     | N/A            | 07-Aug-2019 | 06-Feb-2020 | Reactivation                       |