

Product/Process Change Notifications



PCN - 19 057

Amphenol Information Communication and Commercial Products Group
www.amphenol-icc.com

Release Date: July 15 2019

Product Name:	Millipacs		
	MPACS Right Angle Header		
Product Manager:	Jibu Babu		
Subject:	Notification of Change with Immediate Effectivity		
Distribution:	Affected Customers		
Type of Change:	Process Change		
Change Description:	<p>Top shield gold plating on two sides changed to plating on single side.</p> <div style="text-align: center;"> <p>The diagram illustrates the change in gold plating. On the left, labeled 'Existing', a cross-section of a connector pin is shown with gold plating on both the top and bottom surfaces. A callout box points to both surfaces with the text 'Au plating on both sides'. A green arrow points to the right, labeled 'New Change', where the cross-section shows gold plating only on the bottom surface (the mating side). A callout box points to this surface with the text 'Au plating only on Mating side (Dimple side)'.</p> </div>		
Reason for Change:	As part of product process improvements.		
Affected Parts:	See attached Affected Parts.xls file		
Effective Date of Change:	September 15, 2019		
Last Time Buy Date:	NA		
Earliest Disty Return Date:	NA		
Last Time Shipment Date:	NA		
Datasheet Attached?	NA		
Qual/Test Data Attached?	NA		
Samples Availability Date:	September	15	2019
Available Alternatives?	N/A		
Questions?	<i>Contact your local AICC Representative, or Product Manager</i>		
	Jibu Babu / Product Manager		
	0484 3391946 / Jibu.Babu@fci.com		

Note:
 Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .