

Other Accessories

Fiber Optics

FOC Fiber Optic Patch Cords

A variety of patch cords allow you to test a different type of cable

- FOC-ST/ST, FOC-ST/FC, FOC-ST/SC, FOC-ST/SMA, FOA-ST/STA-Fiber Optic Coupler for FOC-ST/ST Patch Cords

FOM Fiber Optic Meter

The Fluke Fiber Optic Meter (FOM) helps you test and maintain fiber optic cable without having to buy a whole new meter. Plug the FOM directly into any DMM with a mV dc function and a 10 MΩ input impedance and quickly and accurately verify fiber optic cable system loss. Light sources and patch cords sold separately.



FOS 850 & FOS 850/1300 Fiber Optic Light Sources

A variety of light sources allow you to test different cable lengths.



Pressure Module

PV350 Pressure Vacuum Module

- Compatible with all Fluke and most popular DMMs
- Digital pressure and vacuum measurements in a single module
- Transducer sealed in 316 stainless steel compatible with variety of liquids and gases
- Measures vacuum to 76 cm Hg
- Displays results in English (psig of Hg) or metric (kPa or cm Hg) units
- Measures pressure to 500 psig (3447 kPa)




Hanging & Locking Kits

ToolPak

The meter hanging solution


- Kit includes, universal hanger clips (2), hook & loop straps (2 lengths) and strong magnet
- Combine components to meet most hanging needs
- Attaches to back of a 110/170/180 Series meter, 20/70 -III with integrated holster (with adapter), 724/725/789 and 50 Series II



LockPak

The meter locking solution

- Kit includes a locking accessory
- Attaches to back of a 187/189 meter or 724/725/789 to help deter theft
- Accepts most common locks (not included)




High Voltage Probes

80K-6 and 80K-40

A high voltage probe that allows a multimeter to measure up to 6,000V or 40,000V respectively.

Intended for low energy applications only



All accessories have a one year warranty