



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631
www.littelfuse.com

27th January 2022

Attn: All customers

Subject: Update on PSE Mark certification on certain TR/TE fuses of ratings 6.3A and above

Dear Valued Customer,

This letter is to communicate that Littelfuse has received the DENAN Statement of Conformity Assessment (PSE Mark - Certification) required for the Japanese Market for the below fuses and ratings.

Affected TR/TE fuses and ratings are as follows:

- 382 series – 6.3A, 8A, 10A
- 383 series – 6.3A, 8A, 10A
- 400 series – 6.3A

Please see below list of the affected part numbers;





382 SERIES	383 SERIES	400 SERIES
38216300000	38316300000	40016300000
38216300410	38316300410	40016300440
38216300430	38318000000	
38218000000	38318000410	
38218000410	38321000000	
38218000430	38321000410	
38221000000		
38221000410		
38221000430		

The certificate number for the PSE Mark is NBK200122-JP1021. This certificate will replace the JET1896-31007-1006 for the above 382/383/400 ratings which expired on 2021-12-16.

For reference, below is a table of the “before and after” pictures of the markings on the fuse itself and the labels at the end of this letter for the 383 series 6.3A as examples.

Littelfuse will start shipping the affected fuses once the fuses are available.

8755 W. Higgins Road
 Suite 500
 Chicago, IL 60631
www.littelfuse.com

	Before	After
Fuse Marking	 <p>W T 6,3A 300V <PS>E JET cULus 383</p>	 <p>W T 6,3A 300V <PS>E UL - US cULus 383</p>
Label	 <p>38316300000 QTY: 1000 FUSE 300V UL TL TR6 LL AMMO 6.3A CAT NO: 38316300 Time-Lag PS E JET RoHS CE EAC WICKMANN Littelfuse MADE IN PHILIPPINES</p>	 <p>38316300000 QTY: 1000 FUSE 300V UL TL TR6 LL AMMO 6.3A CAT NO: 38316300 Time-Lag PS E UL-US RoHS CE EAC WICKMANN Littelfuse MADE IN PHILIPPINES</p>

Best regards,
 Daniel Wang
 Director OverCurrent Products
 Electronic Business Unit
 Littelfuse, Inc.