



05-Jul-2022

PCN #: PCN-22-144482

Subject : Correct the nut of 1-1423696-6 bootseal from round nut to hex nut

Description of Change : Drafting Error/Omission/Clarification,

1. TE will update the W54 and W57 datasheet for changing the nut of 1-1423696-6 bootseal from round to hex in the future;
2. TE doesn't change the thread of nut for 1-1423696-6 bootseal, it is still M11X1.0 thread, so no influence of the assembly for the 1-1423696-6 bootseal;

Reason : There is a mistake in W54 datasheet and W57 datasheet, the M11X1.0 nut of 1-1423696-6 bootseal was round in those files, but it should be M11X1.0 hex nut for 1-1423696-6 bootseal;

Key Dates :

Contact By Date:07-Jul-2022

Implementation Date:07-Jul-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1-1423696-6			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.