

Title of Change:	4Q2022 Product Discontinuance Notice - Batch 1 (Standard)
Last Time Buy Date:	15 Jun 2023
Last Ship Date:	15 Dec 2023
Contact information:	Contact your local onsemi Sales Office or PCN.Support@onsemi.com
Type of notification:	Customers must notify onsemi (< PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

Description and Purpose:

In an attempt to minimize the number and frequency of product discontinuance notices to its customers, onsemi is publishing this quarterly product discontinuance notification.

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. onsemi continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

onsemi wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

onsemi has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, onsemi has partnered with Rochester Electronics and Flip Electronics who will carry any remaining device inventory to potentially allow for a continued source after onsemi has completed its business process

PLEASE NOTE: onsemi may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

USA

Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ +81 3 6880 1771

Japan

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

Slovakia

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, onsemi ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

To view attached Parts List:

1. Download pdf copy of the PCN to your computer
2. Open the downloaded pdf copy of the PCN
3. Click on the paper clip icon available on the menu provided in the left/bottom portion of the screen to reveal the Attachment field
4. Then click on the attached file/s.

Part Number	Replacement Part	Part Number	Replacement Part
FAN4146SX	-	NC7SV04FHX	-
LC898150XH-MH	-	NC7SV86P5X	-
LE25S81AMDTWG	-	NC7SV00FHX	-
EFC4612R-S-TR	EFC4626R-TR	NC7SP58L6X	-
EFC4615R-TR	-	NC7SP34L6X	-
EFC4621R-TR	-	NC7SP00P5X	-
EFC4C012NLTGDG	-	NC7SP38P5X	-
EFC2K101NUZTDG	-	NC7SV05P5X	-
EFC2K102NUZTDG	EFC2K102ANUZTDG	NC7SV02FHX	-
EFC2K103NUZTDG	-	NC7SP05L6X	-
EFC2K107NUZTCG	-	NC7SP04P5X	-
EFC4K110NUZTDG	-	MC74VHC1GT126MU3TCG	-
EFC4K105NUZTDG	-	MC74VHC1GT126MU2TCG	-
FYP1010DNTU	MBR30H100CTG	MC74VHC1GT126MU1TCG	-
FFB20UP30DNTM	-	MC74VHC1G05DBVT1G	-
FFB20UP20STM	MURB1620CTRT4G	NC7SVL04P5X	-
FFPF20UP20DNTU	MURF1620CTG	NC7SV05FHX	-
FFD10UP20S	MURHD560T4G	NC7SP17L6X	-
FFPF10UP20STU	MUR1520G	NC7SP17FHX	-
NHP160SFT3G	NRVHP160SFT3G	NC7SP08FHX	-
MBR120VLSFT3	MBRM140T1G	NC7SV05L6X	-
NHPAF320T3G	NRVHPAF320T3G	AR0141CS2C00SUEA0-DR	-
NTHS4166NT1G	-	MJD117-1G	MJD117T4G
MBRM110LT1G	MBRM140T1G	MJD253-1G	MJD253T4G
NTMFD4C820NT1G	-	2N6341G	-
MBRM110ET1G	MBRM140T1G	2SA1943RTU	2SA1943OTU
MBRM110ET3G	MBRM140T1G	FJAF43100TU	-
MBRM130LT3G	MBRM140T1G	BDW94CFTU	BDW94C
NTHD3101FT1G	-	FJPF2145TU	-
MBRAF360T3G	NRVBAF2H100T3G	FJPF3305H1TU	-
NTHC5513T1G	-	FJPF3305H2TU	-
NTHD4502NT1G	-	FJPF5027RTU	FJP5027RTU
NTHD4P02FT1G	-	FJPF13007H1TTU	-
NTMFD4C820NAT3G	-	FJPF13009H1TU	-
NTLUS3A18PZTAG	-	FJPF13009H2TU	FJP13009H2TU
NTR3A085PZT1G	-	KSB1017YTU	-
NTLUS3A40PZTAG	-	KSD1408YTU	-
MBR2045EMFST3G	NRVB2045EMFST3G	NLX1G99DMUTCG	-
FDMB3900AN	-	PCISL9R30120W	-
NTNS3C68NZT5G	-	FGH60N60SFDTU	-
FDG6308P	-	FGH60N60UFDTU	-
NTMFS5C430NLAT1G	-	FGH80N60FD2TU	-

NTMFS5C442NLTT3G	-	RHRP15120-F102	-
MBR2045MFST3G	NRVB2045MFST1G	RHRP8120-F102	-
MBR10100MFST3G	NRVB10100MFST1G	FFH60UP60S	-
NTS1545MFST3G	NRVB2045EMFST3G	RURG8060	-
NTS10120MFST3G	NRVTS10120MFST3G	FFH60UP40S	-
MBRD360RLG	MBRD360T4G	NCP630AD2TR4G	-
NTNS3C94NZT5G	-	SS3003CH-TL-E	SS3003CH-TL-W
NTMFS5H425NLT1G	-	FAN2360AMPX	-
CAT24C16DWFA	-	FAN23SV06PAMPX	-
CAT24C32DWFA	-	FAN23SV56AMPX	-
CAT25512DWFA	-	FAN23SV70AMPX	-
CAT853STBI-T3	-	FAN5026MTCX	-
CAT24C08DWFA	-	FAN8060EMPX	-
NLX1G332AMUTCG	NL17SZ332MU1TCG	FDMF2011	-
NLU2G16CMUTCG	MC74VHC2G50MU3TCG	FDMF4061	-
NC7SZ373L6X	-	FDMF5820DC	-
NLU2G17AMUTCG	MC74VHC2G17MU1TCG	FDMF5820TDC	-
NLU2G16MUTCG	MC74VHC2G50MU2TCG	FDMF5821DC	-
NLU2G04MUTCG	MC74VHC2G04MU2TCG	FDMF5822DC	-
NLSF457MU3TCG	-	FDMF5823DC	-
MC74VHC1G86DFT1G	MC74VHC1G86DBVT1G	FDMF5826DC	-
NL17SG02DFT2G	-	FDMF6705	-
NC7SP157L6X	-	FDMF6705B	-
NL17SG17DFT2G	-	FDMF6706C	-
NC7SP74L8X	NC7SP74AL8X	FDMF6820A	-
NLU1G86CMUTCG	MC74VHC1G86MU3TCG	FDMF6820C	-
NL17SG34P5T5G	-	FDMF6823	-
NC7WP125K8X	-	FDMF6823C	-
NC7SP125L6X	-	FDMF6824A	-
NC7WP00K8X	-	FDMF6824C	-
NC7WP02L8X	-	FDMF6840C	-
NC7SV74L8X	NC7SV74AL8X	FDMF6840C3	-
NC7WP125L8X	-	FPF2701MPX	-
NC7WP08K8X	-	FPF2701MX	-
NC7NP14K8X	-	FPF2702MPX	-
NC7NP34K8X	-	NCP1597AMNTWG	-
NC7NP34L8X	-	NCP253171MNTXG	-
M74VHC1GT86DFT1G	-	NCP303150DMNTWG	-
NC7WP32K8X	-	NCP6132AMNR2G	-
NC7WP08L8X	-	NCP81128MNTXG	-
NC7SV126L6X	-	NCP81174NMNTXG	-
NC7WP32L8X	-	NCP81203MNTXG	-
NC7NP14L8X	-	NCP81205FMNTXG	-

74AUP1T97L6X	-	NCP81205MNTXG	-
74AUP1T97FHX	-	NCP81218DMNTXG	-
NC7SV32FHX	-	NCP81218MNTXG	-
74AUP1G97FHX	-	NCP81218PFMNTXG	-
NC7WP14P6X	-	NCP81218PMNTXG	-
NC7SV58P6X	-	NCP81220FHMNTXG	-
M74VHC1GT86DFT2G	-	NCP81220HMNTXG	-
NC7WV14P6X	-	NCP81220MNTXG	-
NL17SG08CMUTCG	-	NCP81226MNTXG	-
NC7SV19P6X	-	NCP81228FDMNTXG	-
M74VHC1GT86DFT1G	MC74VHC1GT86DBVT1G	NCP81228MNTXG	-
NC7SV11P6X	-	NCP81236AMNTXG	-
NC7SV57P6X	-	NCP81236MNTXG	-
MC74VHC1G86DFT2G	-	NCP81236PMNTXG	-
74AUP1G58FHX	-	NCP81266AMNTXG	-
NC7SP04L6X	-	NCP81266FHMNTXG	-
NL17SV04XV5T2G	-	FAN48630BUC31JX	FAN48623UC315X
74AUP1G59L6X	-	NCP349MNAETBG	-
NC7SP58P6X	-	NCP349MNBGTBG	-
NC7SZ10L6X	-	NCP349MNBKTBG	-
74AUP1G57FHX	-	NCP349MNTBG	-
NC7SP19P6X	-	FT7522L6X	-
NL17SG125DFT2G	-	FSA634UCX	FSA636UCX
74AUP1G58L6X	-	FAN54005UCX	FAN54120UC420X
NC7WP14L6X	-	FAN4931IP5X	-
74AUP1G98L6X	-	FAN4852IMU8X	-
NC7SVL32FHX	-	FPF1009	-
NC7SVL08L6X	-	FPF2165R	-
NC7SVL08FHX	-	FSA1259AK8X	-
NC7SVL04L6X	-	FPF2215	-
NC7SV58L6X	-	FPF2193	-
NL17SV02XV5T2G	-	FSA806UMX	-
NC7SV57L6X	-	FSA4157AL6X	FSA5157L6X
NL27WZ02MU1TWG	-	FAN2001MPX	-
SL17SG02P5T5G	-	FSA2257L10X	-
NL17SG34DFT2G	-	FSUSB42UMX-F106	-
MC74VHC1G01DFT1G	-	FAN53601AC182DF	FAN53601UC182X
NL17SG32CMUTCG	NL17SG32MU3TCG	FAN53600AUC33X	FAN53601UC182X
MC74VHC1G05DFT1G	MC74VHC1G05DBVT1G	FAN53600AUC28X	FAN53601UC182X
NLU2G14MUTCG	-	FAN53601AUC10X	FAN53601UC182X
74AUP1G95L6X	-	FSA1257L8X	-
NC7WV16L6X	-	NCP4543IMN5RG-A	-
NC7WV04L6X	-	NCP4545IMNTWG-L	-

NC7SP32L6X	-	NCP45522IMNTWG-H	-
MC74VHC1G05DFT2G	-	NCP45522IMNTWG-L	-
MC74VHC1G05DFT1G	NLVVHC1G05DFT1G	NCP45523IMNTWG-H	-
74AUP1G95FHX	-	NCP45523IMNTWG-L	-
NC7SP00L6X	-	NCP45525IMNTWG-L	-
NLU2G16AMUTCG	MC74VHC2G50MU1TCG	NCP45541IMNTWG-L	-
74AUP1G56L6X	-	NOIL1SN3000A-GDC	-
NC7SV04L6X	-	FS6377-01G-XTD	-
NL17SG125P5T5G	-	FS6377-01G-XTP	-
NL17SV00XV5T2G	-	FS6377-01G-XTD	-
NL7SZ98DFT2G	-	FS7140-01G-XTD	-
NC7SV00L6X	-	FS7140-01G-XTP	-
NL17SG08P5T5G	-	FS7140-02G-XTD	-
MC74VHC1G86DBVT1G	-	FS7140-02G-XTP	-
NC7SV86L6X	-	FNE41060	NFAQ1060L36T
NL37WZ06USG	-	MC34067DWR2G	-
NC7SV14L6X	-	NCL30188ADR2G	NCL30488B1DR2G
NLU2G06MUTCG	-	NCL30386A1DR2G	NCL30486B2DR2G
NC7SV19L6X	-	NCL30386A2DR2G	NCL30486B2DR2G
MC74VHC1G01DTT1G	MC74VHC1G01DBVT1G	NCL30386B1DR2G	NCL30486B2DR2G
NC7SP32P5X	-	NCL30388A1DR2G	NCL30488B1DR2G
NC7SP02L6X	-	NCL30388B1DR2G	NCL30488B1DR2G
NL27WZ02MU2TCG	-	NCL30486A1DR2G	NCL30486B1DR2G
NL27WZ08MU1TCG	-	NCL30486A2DR2G	NCL30486B2DR2G
NL27WZ02MU1TCG	-	NCL30488A2DR2G	NCL30488B2DR2G
NL7SZ98DBVT1G	-	NCL30488A3DR2G	NCL30488B1DR2G
NC7SP05P5X	-	NCL30488A4DR2G	NCL30488B4DR2G
MC74VHC1G01DFT2G	-	NCP431AVLPRAG	-
NC7SV32L6X	-	NCP4353BSNT1G	NCP4328BSNT1G
NC7SP04FHX	-	TL431ACLPRPG	TL431ACLPRAG
NC7SP86L6X	-	TL431AILPRPG	TL431AILPRAG
NL17SG02P5T5G	-	TL431BCLPRMG	TL431BCLPRAG
NL17SGU04P5T5G	-	TL431BVLPG	TL431BILPRAG
NL27WZ08MU2TCG	-	TL431BVLPRAG	TL431BILPRAG
NL17SG126DFT2G	-	TLV431BLPRAG	-
NL17SG07P5T5G	-	NUF4401MNT1G	-
NL17SG04DFT2G	-	1N5934BRNG	1N5934BG
NL17SG00DFT2G	-	NSR05T404MX2T5G	NSR05F40NXT5G
NC7WV14L6X	-	J58	-
NC7SZ386L6X	-	HBL1009RP	-
NC7SZ374L6X	-	HBL1009MRP	-
NC7SZ27L6X	-	HBL2010BRP	-
NC7SP157P6X	-	ESD11B5.0SBT5G	-

NC7SP34P5X	-	ESD7471N2T5G	-
NC7SV02P5X	-	ESDM1031MX4T5G	-
NC7SP86P5X	-	ESDM1131MX4T5G	-
NC7SVU04L6X	-	MM3Z27VC	-
NC7SV17L6X	-	MM3Z62VC	-
NC7SP02P5X	-	MMBZ39VCLT1G	-
NC7SV57FHX	-	MMSZ4684T3G	MMSZ4684T1G
NC7SV17FHX	-	MMSZ5235BT3G	MMSZ5235BT1G
NC7SV02L6X	-	MJD31C1G	MJD31CT4G