



Pushing Performance

Date: 01/28/25

## PRODUCT RETURN NOTIFICATION

Dear Valued Customer,

This is to notify you about that you may have received the piece that have burr on the fixing clips associated with deliveries of HARTING part numbers **09451511120** & **09451511560**.

Please see the impacted “**Batch Numbers**” for HARTING Part Numbers associated with this return. This defect can be easily found on the part.

| Part Number        | Batch Numbers                                      |
|--------------------|--|
| <b>09451511120</b> | 0225D238R03, 0225D426R03                           |
| <b>09451511560</b> | 5024D645R04, 5124D537R04, 0225D929R04, 5224D931R04 |

OK



NOK



If you received parts that have a burr on the fixing clips, they should be returned to HARTING. For return orders, please contact your HARTING customer service representative and identify that you have product to return, and the concern will be addressed with replacement parts as needed.

We at HARTING sincerely apologize for this matter and will work to replace your parts, if affected, as quickly as possible.

If your parts do have a burr on the fixing clips, there is no concern, and you can disregard this notification.

Sincerely,

A handwritten signature in black ink that reads "Edgar Jimenez". The script is fluid and cursive, with the first letters of each word being capitalized and prominent.

Edgar Jimenez  
Supplier Quality Engineer