

USB2.0 HUB

pro-SIGNAL

7 Port



Features:

- Compatible universal serial bus specification revision 2 (data rate 1.5 / 12 / 480 Mbps)
- Connects up to 127 USB devices
- Bus-power and self-power mode used
- Plug-and-play function
- 1 upstream and 2/4/7 downstream USB ports included
- Over-current detection and protection

Safety Instructions

Always read the safety instructions carefully:

- Keep this User's Manual for future reference
- Keep this equipment away from humidity
- If any of the following situation arises, get the equipment checked by a service technician:
 1. The equipment has been exposed to moisture
 2. The equipment has been dropped and damaged
 3. The equipment has obvious sign of breakage
 4. The equipment has not been working well or you cannot get it work according to user's manual

Copyright Statement

No part of this publication may be reproduced in any form by any means without the prior written permission. Other trademarks or brand names mentioned herein are trademarks or registered trademarks of their respective companies

Disclaimer

Information in this document is subject to change without notice. The manufacturer does not make any representations or warranties (implied or otherwise) regarding the accuracy and completeness of this document and shall in no event be liable for any loss of profit or any commercial damage, including but not limited to special, incidental, consequential, or other damage

Installation Verification

- After you connect this hub to PC by a USB cable, the system will detect the device and install the required drivers automatically.
- After installation finished, you can go to Device Manager to verify the completed installation*


*According to previous description, the driver is based on host system. The following image is based on USB 1.1 hub installed. The device name may be varied on your host

USB2.0 HUB


pro-SIGNAL

7 Port


Windows 98SE/ME



Windows 2000/XP/Vista



Mac OS



www.element14.com
www.farnell.com
www.newark.com
www.cpc.co.uk

pro-SIGNAL

USB2.0 HUB

7 Port

Remark


If your operation system is Windows ME, which will have a green question mark shown in Device Manager. It is all right because Windows ME cannot identify the USB Hub's brand but it won't have any impact on its function

Mac OS : After installation finished, please go to Apple System Profile > Device and Volumes > USB to verify the installation completed.

Over-Current Status Figure

If there is a pop-up window, "USB Hub Current Limit Exceeded", please click reset to resume work or you can reset the hub by unplugging the USB cable and plugging it back

When the excessive current happens, the over-current protection will disconnect power from the related port and turn off the green LED



Part Number Table

Description	Part Number
HUB, USB 2.0, External, 7Port	HU2772

Important Notice : This data sheet and its contents (the "Information") belong to the members of the Premier Farnell group of companies (the "Group") or are licensed to it. No licence is granted for the use of it other than for information purposes in connection with the products to which it relates. No licence of any intellectual property rights is granted. The Information is subject to change without notice and replaces all data sheets previously supplied. The Information supplied is believed to be accurate but the Group assumes no responsibility for its accuracy or completeness, any error in or omission from it or for any use made of it. Users of this data sheet should check for themselves the Information and the suitability of the products for their purpose and not make any assumptions based on information included or omitted. Liability for loss or damage resulting from any reliance on the Information or use of it (including liability resulting from negligence or where the Group was aware of the possibility of such loss or damage arising) is excluded. This will not operate to limit or restrict the Group's liability for death or personal injury resulting from its negligence. pro-SIGNAL is the registered trademark of the Group. © Premier Farnell plc 2012.