P.O. Box 14460 St. Louis, MO 63178-4460

114 Old State Road Ellisville, MO 63021-5942 (636) 394-2877



Date: May 22, 2012

To: KAA High Speed Fuse Customers Subject: KAA Series End-of-Life Notice

Effective May 22, 2012, the KAA Series reached its end-of-life and is no longer available. The specific part numbers are listed in the table below along with their suggested replacements. There is no last time buy.

Discontinued Part #	Discontinued Part # UPC Code	Replacement Part	Replacement Part # UPC Code
KAA-1/2	051712430005	*	*
KAA-1	051712430012	*	*
KAA-1-1/2	051712432658	*	*
KAA-2	051712430029	*	*
KAA-3	051712430036	*	*
KAA-4	051712430043	*	*
KAA-5	051712430050	FWA-5A10F	051712795197
KAA-6	051712430067	*	*
KAA-7	051712430074	*	*
KAA-8	051712430081	*	*
KAA-9	051712430098	*	*
KAA-10	051712430104	FWA-10A10F	051712795203
KAA-12	051712430128	*	*
KAA-15	051712430159	FWA-15A10F	051712795210
KAA-20	051712430203	FWA-20A10F	051712795227
KAA-25	051712430258	FWA-25A10F	051712795234
KAA-30	051712430302	FWA-30A10F	051712795241

^{*}Contact Applications Engineering for replacement.

The following points address common questions regarding this end-of-life notice:

- The KAA and FWA have the same form, fit and function.
- To review the performance characteristics of the FWA, see data sheet # 720003 online at www.cooperbussmann.com/DatasheetsEle.
- Any of the above part numbers you may have in stock are still usable and should not be returned.

For any further questions regarding this notice, please contact your local Cooper Bussmann representative.

Cordially,

Jason Ezzell Product Manager Cooper Bussmann