

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	001	025	0000000205	See list below	Circuit Protection	USF 1206 0.5 A	n/a

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected			
3413.0113.11	3413.0113.22	3413.0113.24	3413.0113.26

2 Type of change

- Change of marking
- Change of material

3 Detailed description of change

Old product appearance	New product appearance
	

4 Reason of change

- Symmetric marking to provide improved marking readability independent from device placement in blister.
- Change of body material due to material phase out.

5 Release date

The change takes effect in ww 03/2017 (Date code 2017 or higher on label).

6 Impact of change and recommended action

Form	Yes	Changed marking and new body material
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	USF 1206

Product Change Notification						USF 1206 0.500 A, PCN	
owner	creation date	release date	released by	change order no	rev	page	D10-012-696
ganderka	2017-01-13	2017-01-23	nowakfr	2011960	A	1 of 1	