



Product Change Notification

Current Date: 08-Apr-2019

TE Connectivity

Product Change Notification: E-19-005408

PCN Date: 05-APR-19

Customer: Waldom Electronics Corp (167882)

Location: Rockford

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Superseding of VERSAFIT & VERSAFIT-3X -SP & -STK parts migrating from Menlo Park, USA to Trutnov, CZ.

Description of Changes
The following part numbers are being superseded (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application.
Other attachments:
[PCN VERSAFIT Products affected part numbers.](#)
[PCN VERSAFIT Products Notification](#)

Reason for Changes:
Discontinuance. Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. The affected part numbers have previously been identified & notified within PCN P-17-014047 as parts migrating from Menlo Park, USA to Trutnov, CZ for manufacturing using new part numbers. The sales UOM for the replacement part numbers will change from FT to PC for all -STK part numbers, and from FT to Metre for all -SP part numbers.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
07-AUG-2019	
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
01-OCT-2019	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
030791-000	YES			7-1190238-4, VERSAFIT-3/4-0-FSP	NB14354001		Sales UOM change.
0313754004	YES			5-1190243-7, VERSAFIT-1/2-2-SP	NB14164001		Sales UOM change.
1550634001	YES			6-1191120-8, VERSAFIT-3/8-0-FSP	NB14474001		Sales UOM change.
2748174003	YES			5-1192035-7, VERSAFIT-3/32-6-SP	NB20494001		Sales UOM change.
4812454003	YES			5-1193602-6, VERSAFIT-3-0-SP	NB17804001		Sales UOM change.
5058684016	YES			5-1193905-6, VERSAFIT-3/32-0-SP	NB20424001		Sales UOM change.
5058704033	YES			1193906-3, VERSAFIT-1/8-0-SP	NB20164001		Sales UOM change.
5058724002	YES			5-1193906-0, VERSAFIT-3/16-0-SP	NB20274001		Sales UOM change.
5058734012	YES			9-1193906-4, VERSAFIT-3/16-9-SP	NB20394001		Sales UOM change.
5058744001	YES			1193907-8, VERSAFIT-1/4-0-SP	NB20034001		Sales UOM change.
5058764004	YES			7-1193907-5, VERSAFIT-3/8-0-SP	NB14494001		Sales UOM change.
5058784018	YES			2-1193908-7, VERSAFIT-1/2-0-SP	NB14134001		Sales UOM change.
5562734018	YES			2-1194388-0, VERSAFIT-1/16-0-SP	NB19914001		Sales UOM change.
6679894002	YES			5-1195260-8, VERSAFIT-4-0-SP	NB17824001		Sales UOM change.

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
721053-000	YES			6-1195638-4, VERSAFIT-1/2-0-FSP	NB14124001		Sales UOM change.
9621714002	YES			3-1197443-7, VERSAFIT-3/4-3-SP	NB14404001		Sales UOM change.