




# Product Change Notification (PCN)

PCN Number	508845	Date Issued	September 01, 2020
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	Dimension analysis		
Internal Molex Qualification Date	May 08, 2020		
Sample Availability Date (Changed Part)	May 08, 2020		
Planned Implementation Date	September 01, 2020		
Method of Identifying Change	Factory order number		

RELEASED

**Before Change**

**After Change**



**Overview**

- We are changing the sub-product element form in order to meet our product conformance;
  - A sub-product element known as a metal angle plate is getting changed. This metal angle plate was sticking to the hoods of the connector and was getting pressed in the current design. This is undesirable. Cutouts for reverse use are added. Change of the outer geometry to enable reverse application in the connector is also enabled.
- **Product Impact**
  - There is impact to form/appearance of the product
  - No impact on Function and Fit
- **Part Number Impact**
  - See attached impacted parts list
- Qualification Reports and samples available upon request after the date shown above





## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:508845**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

PCN #	Customer#	Customer Name	Search Term	Molex Part#	Customer Material #	City
508845	103989	TTI INCORPORATED	TTIINCORPO	732990880	MOL73299-0880	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1120160018	MOL112016-0018	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731070300	MOL173107-0300	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731070302	MOL173107-0302	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731070303	MOL173107-0303	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731070356	MOL173107-0356	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731070375	MOL173107-0375	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731070379	MOL173107-0379	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731070383	MOL173107-0383	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731090381	MOL173109-0381	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731090466	MOL173109-0466	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731091881	MOL173109-1881	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731091882	MOL173109-1882	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731130153	MOL173113-0153	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731130154	MOL173113-0154	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731130158	MOL173113-0158	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731140213	MOL173114-0213	FORT WORTH
508845	103989	TTI INCORPORATED	TTIINCORPO	1731140266	MOL173114-0266	FORT WORTH