



The parts affected are as follows:-

4719270 2002-402


4719281 2002-403

4719293 2002-404

4719300 2002-405

2579871 2002-410

The change is to correct an error in the marking regarding the current rating and does not affect the fit or function of the parts. Old and new parts can be used together and part numbers will not change.

<i>Change Description</i>	Old Condition	New Condition
	The molded title block on the jumper says 24A 	The molded title block on the jumper says 25A, as it should

This change will be integrated over the next 6 to 12 months, delivery of old and new parts together is possible.

If you require any further information then please let me know.

With Best Regards,

**WAGO Limited**