

Product Change Notification

urrent Date: 24-Oct-2022

TE Connectivity

Product Change Notification: P-22-023343 PCN Date: 08-SEP-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Mold transfer from Baby inection machine to Conventional injection machine for connector components

Description of Changes

In order to improve the injection quality of our parts, we have decided to transfer several components (TPAs and CPAs) from Babyplast injection machines to conventional injection machines. Conventional injection mold machines are more stable and therefore our components are expected to have a more reliable injection process that will positively affect the quality of our connectors.

Other attachments:

PDF file includes proposed validation test for each PN

Reason for Changes:	
Product improvement. Please find attached the proposed	d validation test we intend to follow to evaluate the connectors performance after the components process
modification.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	28-FEB-2023
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

r are rearriber(s)	being Modified:		 	1	1	
Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1-1438608-5</u>	NO					
<u>1-1438608-6</u>	NO					
<u>1-1718643-1</u>	NO		"EG9733-000", "AMP-1-1718643-1"			
<u>1-1718643-2</u>	NO					
<u>1-1718643-3</u>	NO					
<u>1-1718644-2</u>	NO					
<u>1-1718644-6</u>	NO					
<u>1-1718645-1</u>	NO					
<u>1-1718645-3</u>	NO					
<u>1-1718645-9</u>	NO					
<u>1-1823608-4</u>	NO					
<u>1-1823608-5</u>	NO					
<u>1-2289032-1</u>	NO					
<u>1599422-1</u>	NO					
<u>1599423-1</u>	NO					
<u>1599427-1</u>	NO					
<u>1599428-1</u>	NO					
<u> 1599429-1</u>	NO					
<u>1599572-1</u>	NO					
<u>2-1438608-1</u>	NO					
<u>2-1718644-1</u>	NO					
<u>2-1718644-2</u>	NO					
<u>2-2289033-1</u>	NO					
<u>2310298-1</u>	NO					
<u>2319841-1</u>	NO					
<u>2319841-2</u>	NO					
<u>2321165-1</u>	NO					
2339443-1	NO					
282080-1	NO		"CM8390-000", "AMP-0-0282080-1", "2-42939-6211", "8202611296", "8202613264"			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>282080-3</u>	NO					
<u>282080-4</u>	NO					
3-1718643-2	NO					
<u>444079-1</u>	NO					
<u>444496-1</u>	NO					
<u>444496-7</u>	NO					
<u>828647-1</u>	NO					
<u>828648-1</u>	NO					
<u>881565-1</u>	NO					
<u>881566-1</u>	NO					
<u>881735-1</u>	NO					
<u>963121-2</u>	NO					