



Tuesday 21<sup>st</sup> February 2023

Dear Customer,

**Re: Obsolescence notification for Harwin product.**

Please be advised that the following part numbers are now obsolete with immediate effect.

- M40-600xx46
- **NOTE:** M40-600xx46R are not affected, and are still available – these are identical connectors, but packaged in tape & reel

Please see the following spreadsheet for a detailed list of affected items:

[https://cdn.harwin.com/pdfs/Obsolescence\\_notification\\_spreadsheet\\_2023-02-21.xlsx](https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_2023-02-21.xlsx)

Unfortunately, we are no longer able to support this packing variation on these product ranges. Alternative items are available; please see the attached list for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team  
[technical@harwin.com](mailto:technical@harwin.com)