



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001097I

DATE: 28-Aug-2023

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DG418DJ+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1077Z-203+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1077Z-203+T&R	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1100LU-300+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1250YP-70+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1343D-3+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	DS1343D-3+T&R	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	DS2149Q+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	DS2149Q+T&R	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	DS28CN01U-W0T+1T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX14690JEWX+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX14690JEWX+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX14720EEWA+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX14720EEWA+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX15069ATP+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX15069ATP+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX16039LLA23+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX16039LLA23+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX16512GFO+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX16512GFO+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX17058X006+T10	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX1740EUB+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX1809ETI+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX1809ETI+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX187CEPA+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX19995ETX+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 28-Sep-2023

Discontinuance	MAX19995ETX+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX2059ETL+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX2059ETL+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX3318EEAP+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX4282EUA+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX4522CPE+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX481EEPA+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX4917BELT+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX4917BELT+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5006BCUB+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5069AAUE+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5099ATJ+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5099ATJ+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5201BEUB+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5201BEUB+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5857EXE+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5857EXE+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5866ETM+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5929ALEEG+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5941AESE+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX5941AESE+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6034BEXR41+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6034BEXR41+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6307UK46D3+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6307UK46D3+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6314US25D1+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6314US25D1+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6330SUR+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6330SUR+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6336US22D3+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6336US22D3+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6338GUB+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6338GUB+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6380XR46+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6380XR46+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6381XR29D4+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 28-Sep-2023

Discontinuance	MAX6381XR29D4+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6385XS16D3+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6385XS16D3+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6385XS31D3+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6385XS31D3+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6424UK23+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6424UK23+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6467XS26D7+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6467XS26D7+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6694UE9A+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6717AUKRVD3+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6717AUKRVD3+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6718AUKSHD3+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6718AUKSHD3+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6831VFUT+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX6831VFUT+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX709TEPA+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX867EUA+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX867EUA+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX8877EUK32+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX8877EUK32+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX9589AUB+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX9589AUB+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EFF+CPM	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EFF+CPN	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EFF+CQA	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EFF+TCPM	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EFF+TCPN	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EFF+TCQA	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EWA+CPM	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EWA+CPN	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EWA+CQA	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EWA+TCPM	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EWA+TCPN	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX98373EWA+TCQA	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAX984CSE+	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 28-Sep-2023

Discontinuance	MAX984CSE+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAXQ636V-2584+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAXQ636V-2591+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	MAXQ636V-2606+T	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	VT263BWFQX-ADJ	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured
Discontinuance	VT505BFQ	N/A	28-Aug-2023	26-Feb-2025	Part can no longer be manufactured