



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

Notification#20240203000.0
Pin One Device symbolization update for Select SOT Devices
Information Only

Date: February 5, 2024
To: Newark/Farnell PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the Change Management team.

Sincerely,

Change Management Team
SC Business Services

20240203000.0
Attachment: 1

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, you have recently purchased these devices. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
ADS1100A2IDBVTG4	NULL
ADS7886SDBBVT	NULL
DRV5013ADQDBZR	NULL
INA195AIDBVT	NULL
INA219AIDCNR	NULL
LM1117IMP-5.0/NOPB	NULL
LM1117MP-3.3/NOPB	NULL
LM2731YMF/NOPB	NULL
LM2776DBVT	NULL
LM2831XMF/NOPB	NULL
LM2841XMK-ADJL/NOPB	NULL
LM2842XMK-ADJL/NOPB	NULL
LM2936MP-3.0/NOPB	NULL
LM2936MP-5.0/NOPB	NULL
LM2937IMP-12/NOPB	NULL
LM2937IMPX-15/NOPB	NULL
LM2940IMP-5.0/NOPB	NULL
LM2940IMP-9.0/NOPB	NULL
LM317EMP/NOPB	NULL
LM317LIPK	NULL
LM317MDCY	NULL
LM3480IM3-12/NOPB	NULL
LM3671MF-3.3/NOPB	NULL
LM3940IMP-3.3/NOPB	NULL
LM4040C41IDBZR	NULL
LM4040CIM3-4.1/NOPB	NULL
LM5050MK-1/NOPB	NULL
LM7301IM5/NOPB	NULL
LMC7111BIM5X/NOPB	NULL
LMH6624MF/NOPB	NULL
LMH6642MF/NOPB	NULL
LMP7701MF/NOPB	NULL
LMR14203XMK/NOPB	NULL
LMR14206XMK/NOPB	NULL
LMV321IDBVR	NULL
LMV321M5/NOPB	NULL
LMV331IDBVR	NULL
LMV431AIMF/NOPB	NULL
LMV651MF/NOPB	NULL
LMV841MG/NOPB	NULL
LP2981AIM5-3.3/NOPB	NULL
LP2981IM5-3.3/NOPB	NULL
LP2985A-33DBVTE4	NULL
LP2985AIM5-3.3/NOPB	NULL
LP2985AIM5-5.0/NOPB	NULL
LP2985IM5-3.0/NOPB	NULL
LP2992AIM5-3.3/NOPB	NULL
LP3855EMP-ADJ/NOPB	NULL

LP38692MP-5.0/NOPB	NULL
LP3961EMP-3.3/NOPB	NULL
LP3964EMP-2.5/NOPB	NULL
LP5907MFX-3.3/NOPB	NULL
OPA188AIDBVT	NULL
OPA317IDBVT	NULL
OPA320AIDBVT	NULL
OPA365AIDBVR	NULL
OPA378AIDBVT	NULL
REF1112AIDBZT	NULL
REG1117-3.3	NULL
REG1117-5/2K5	NULL
SN6501DBVT	NULL
SN65LVDS2DBVT	NULL
SN74AHCT1G125DBVR	NULL
SN74LVC1G07DBVR	NULL
SN74LVC1G08DBVRG4	NULL
SN74LVC1G11DBVR	NULL
SN74LVC1G14DBVR	NULL
SN74LVC1G175DBVR	NULL
SN74LVC1G3157DBVR	NULL
SN74LVC1G32DBVR	NULL
SN74LVC1G97DCKR	NULL
SN74LVC1GX04DBVR	NULL
SN74LVC2G17DCKRG4	NULL
TL1963ADCQR	NULL
TL331IDBVR	NULL
TL431IDBVR	NULL
TLV1117LV18DCYR	NULL
TLV271IDBVR	NULL
TLV431ACDBZR	NULL
TLV431IDBZR	NULL
TLV70028DDCT	NULL
TPD4E001DRLR	NULL
TPS3808G33DBVR	NULL
TPS3808G33QDBVRQ1	NULL
TPS3838K33DBVT	NULL
TPS563200DDCT	NULL
TPS564201DDCT	NULL
TPS60400DBVT	NULL
TPS60403DBVT	NULL
TPS61041DBVR	NULL
TPS61097-33DBVT	NULL
TPS62203DBVT	NULL
TPS64202DBVR	NULL
TPS64202DBVT	NULL
TPS71550DCKR	NULL
TPS76301DBVR	NULL
TPS76301DBVT	NULL
TPS76333DBVT	NULL
TPS79328DBVRG4	NULL
TPS79501DCQG4	NULL
TPS79901DDCR	NULL
TPS79930DDCT	NULL
TS5A3166DCKR	NULL
TXB0101DBVR	NULL
UA78M05CDCYG3	NULL

Technical details of this Product Change follow on the next page(s).

Notification Number:	20240203000.0	Notification Date:	Feb 5, 2024
Title:	Pin one Device symbolization update for Select SOT Devices		
Customer Contact:	Change Management team	Dept:	Quality Services
Change Type:			
☐	Assembly Site	☐	Design
☐	Assembly Process	☐	Data Sheet
☐	Assembly Materials	☐	Part number change
☐	Mechanical Specification	☐	Test Site
☒	Packing/Shipping/Labeling	☐	Test Process
☐	Wafer Bump Material	☐	Wafer Bump Process
☐	Wafer Fab Site	☐	Wafer Fab Materials
☐	Wafer Fab Process	☐	

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an update to the pin one designator on select SOT devices as follows:


Current	Proposed
Pin One Stripe only	Pin One Stripe or Pin one Dot

Following this notification, devices can be shipped with either the pin one stripe or the pin 1 dot.

See example below:

Topside Symbol Compare: PHI A/T

TLV2370IDBVR Topside Symbol




Pin 1 Dot Topside Symbol



Pin 1 Stripe Topside Symbol



Topside Symbol	: SOT23
+-----+ ***** = BINARY DATECODE PER TI	
! [] * * * * !	DRAWING # 4205087
! [] VBFI !	
! [] * * * * !	
+-----+ LINE MAXIMUM IS 4 CHARACTERS	
[] PIN ONE STRIPE (MARKED)	



Reason for Change:

Improved internal traceability

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Device marking change only

Changes to product identification resulting from this notification:

Device marking change only. No change to pack labels.

Product Affected:

See page 2

For questions regarding this notice, e-mails can be sent to Change Management team or your local Field Sales Representative.

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES “AS IS” AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, or other requirements. These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI’s products are provided subject to TI’s Terms of Sale (www.ti.com/legal/termsofsale.html) or other applicable terms available either on ti.com or provided in conjunction with such TI products. TI’s provision of these resources does not expand or otherwise alter TI’s applicable warranties or warranty disclaimers for TI products.