



infrastructure for a connected world

## PRODUCT CHANGE NOTIFICATION

Product Category INDUSTRIAL NETWORKS PRE-CONFIGURED **20240117-1**

Product Group INDUSTRIAL NETWORKS

ISSUE DATE:  N/A  EMEA  LATAM  AP Jan-24

IMPACTED REGIONS:  DISCONTINUATION

REASON FOR CHANGE:  OTHER

### DESCRIPTION OF CHANGE: (Required)

We will be discontinuing FDME8RG, Fiber DIN Mount Patch Panel with 8 dedicated ports. FDME8RG is being replaced with FDPPSIG and FDPPEIG. The FDPPSIG is a standard depth panel, that will accept most Fiber Adapter Panels (FAPs). The FDPPEIG is an extended depth panel that will accept most FAPs or OptiCom® cassettes. Please use part number FDPPSIG with FMP6 for closest cross with six Mini-Com® modules. Other FAPs can be used to achieve similar or higher fiber port densities as FDME8RG.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	6	1
Old product discontinuation date*	2024	4	16

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

**CUSTOMER SERVICE CONTACTS**

<b>ASIA PACIFIC</b>	<b>AUSTRALIA: 1-800 7263848</b> <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	<b>CHINA: 400-820-1900</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	<b>HONG KONG: 800-965768</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>
	<b>INDIA: 000 800 6501844 (Fixed)</b> 000 800 6500369 (Mobile)  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>INDONESIA: 001 803 65 7571</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>JAPAN: +81-3-6863-6000</b>  <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>
	<b>KOREA: 02-2182-7300</b> <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	<b>MALAYSIA 1800 801435</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>SINGAPORE: 1-800-7263848</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>
	<b>TAIWAN: 0080 165 1487</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>THAILAND: 001-800-65-6385</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
<b>LATIN AMERICA</b>	<b>BRAZIL 08000562613 (Toll Free)</b>  <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	<b>MEXICO: +52-33-37776000 x80520</b> 01 800 360 86 00 (Toll Free)  <a href="mailto:MEX-customerservice@panduit.com">MEX-customerservice@panduit.com</a>	<b>OTHER LA COUNTRIES:</b> Phone USA 1-708-532-1800  <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>
<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300  <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b>	<b>EMEA: +44 208 6017219</b>  <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>

IMPACTED PART NUMBER	Replacement Part
FDME8RG	FDPPSIG