

Document Receipt Acknowledgement



Document Number: D07718-A-G0190

Date: Jun. 15, 2024

Date:  
Section:  
Name:

Attention:

**FARNELL ELEC COMPONENTS**

**LTD**

**Notification of Anamizu Factory Earthquake Recovery, Return to Production & Yokaichi Factory Support**

Winding type Common mode choke coil DLW5A/DLW5B series  
Chip inductor LQH2HNNH\_03, LQH2HPN/Z/H\_GR, LQH2HPZ\_JR, LQH32NZ/H\_23, LQH3NPN/Z/H\_ME, LQH43CN\_03, LQH43NN/Z/H\_03, LQH43PN/Z/H/B\_26 series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.  
This is the official notification that some of our products detailed below.  
Your understanding and support are highly appreciated.

**1. Product Type and Customer/Murata Part Numbers:**

Product Type: DLW5A/DLW5B series  
LQH2HNNH\_03, LQH2HPN/Z/H\_GR, LQH2HPZ\_JR, LQH32NZ/H\_23, LQH3NPN/Z/H\_ME, LQH43CN\_03, LQH43NN/Z/H\_03,  
LQH43PN/Z/H/B\_26 series

Please refer to the attached documents for Part Numbers' information.

**2. Background/Request:**

The above listed series are produced at our Anamizu Factory  
The Anamizu factory was affected by the 2024 Noto Peninsula earthquake that occurred on January 1, 2024.  
We have been working to restore the plant as quickly as possible.

Anamizu factory production resumed May 13. 2024

It will take some time to get Anamizu factory to go to full capacity.  
At this time, we will continue temporary production at our Yokaichi Factory for these products until this process is complete  
Thank you for your understanding in supplying the restarted products at the Anamizu Factory.

Please note that there are no changes for 4M (Man, Machine, Material, Method).

**3. Contact Window:**

Should you have any questions or concerns,  
please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.  
Marketing & Promotion Department EMI Filter  
Division  
Hiromi Nagasaka